#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 23V-565

**Manufacturer Name:** Chrysler (FCA US, LLC)

Submission Date: AUG 10, 2023 NHTSA Recall No.: 23V-565 Manufacturer Recall No.: 84A



#### **Manufacturer Information:**

Manufacturer Name: Chrysler (FCA US, LLC)

Address: 800 Chrysler Drive

CIMS 482-00-91 Auburn Hills MI

48326-2757

Company phone: 1-800-853-1403

## **Population:**

Number of potentially involved: 16 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2023-2023 Jeep Wrangler

Vehicle Type:

Body Style: SUV Power Train: NR

Descriptive Information : Some 2023 MY Jeep Wrangler vehicles may be equipped with a spare tire carrier

assembly built with an incorrect center high mount stop lamp ("CHMSL") bracket

assembly.

The suspect period began on February 9, 2023, when suspect spare tire carrier assemblies were introduced into vehicle production, and ended on February 14, 2023, when suspect spare tire carrier assemblies were no longer used in vehicle production. Production and supplier records were used to identify the suspect period.

Similar vehicles not included in the recall were built with a correct spare tire carrier

assembly, or were built before or after the suspect period.

Production Dates: FEB 09, 2023 - FEB 14, 2023

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

### **Description of Noncompliance:**

Description of the Federal Motor Vehicle Safety Standard ("FMVSS") No. 571.108 S6.1.3.1 requires

Noncompliance: that "Each lamp...must be securely mounted...and in a location where it

complies with all applicable photometric requirements in S7.9.13 Photometry. Each high-mounted stop lamp must be designed to conform to the photometry requirements of Table XV...". Subject vehicles do not meet these photometry

requirements.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: A CHMSL that is partially obstructed may not have adequate conspicuity to

other drivers to indicate the intention to slow or stop, which can cause a

crash without prior warning.

Description of the Cause: NR

Identification of Any Warning None

that can Occur:

### **Involved Components:**

Component Name 1 : Spare Tire Carrier Assembly

Component Description: Carrier Assembly - Spare Tire

Component Part Number: 68479193AC

#### **Supplier Identification:**

## **Component Manufacturer**

Name: GRAMMER AMERICAS

Address: 1429 COINING DR

TOLEDO Ohio 43612-2932

**Country: United States** 

#### **Chronology:**

- On April 18, 2023, the FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") organization opened an investigation into 2023 MY Jeep Wrangler vehicles built with a spare tire carrier assembly which may result in the spare tire obstructing the CHMSL.
- From April 2023, through July 2023, FCA US TSRC reviewed vehicle records and met with FCA US Engineering, FCA US Supplier Quality, and the supplier to review manufacturing and supplier data to understand the condition and determine the suspect population.
- On July 12, 2023, FCA US TSRC recognized a vehicle build issue exists on certain vehicles related to an obstructed CHMSL, potentially resulting in a noncompliance with FMVSS No. 108.
- On August 3, 2023, FCA US determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

### **Description of Remedy:**

Description of Remedy Program: FCA US will conduct a voluntary safety recall on all affected vehicles to replace the spare tire carrier assembly.

> FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.

How Remedy Component Differs The remedy component will be a spare tire carrier assembly that meets

from Recalled Component: FMVSS No. 108 Photometry requirements.

Identify How/When Recall Condition NR was Corrected in Production:

#### **Recall Schedule:**

Description of Recall Schedule: \*\*08/10/2023: FCA US will notify dealers and begin notifying owners on

or about 09/29/2023.

Planned Dealer Notification Date: SEP 29, 2023 - SEP 29, 2023 Planned Owner Notification Date: SEP 29, 2023 - SEP 29, 2023

\* NR - Not Reported