# Part 573 Safety Recall Report

Manufacturer Name :Porsche Cars North America, Inc.Submission Date :JUL 28, 2023NHTSA Recall No. :23V-527Manufacturer Recall No. :APB1



23V-527

## Manufacturer Information :

Manufacturer Name :Porsche Cars North America, Inc.Address :One Porsche DriveAtlanta GA 30354Company phone :1-800-767-7243

## **Population :**

Number of potentially involved : 2,934 Estimated percentage with defect : 100 %

## Vehicle Information :

Vehicle 1:	2024-2024 Porsche Cayenne
Vehicle Type :	LIGHT VEHICLES
Body Style :	SUV
Power Train :	GAS
Descriptive Information :	Affected vehicles have been identified through production records.
Production Dates :	MAR 23, 2023 - JUN 23, 2023
VIN Range 1:1	Begin : WP1AA2AY5RDA00033 End : WP1AA2AY4RDA03618 🗌 Not sequential
Vehicle 2:	2024-2024 Porsche Cayenne S
Vehicle Type :	LIGHT VEHICLES
Body Style :	
Power Train :	GAS
Descriptive Information :	Affected vehicles have been identified through production records.
<b>Production Dates :</b>	APR 20, 2023 - JUN 23, 2023
VIN Range 1:1	Begin :    WP1AL2AY1RDA32021    End :    WP1AL2AY0RDA33015    Not sequential
Vehicle 3:	2024-2024 Porsche Cayenne Coupe
Vehicle Type :	LIGHT VEHICLES
Body Style :	
Power Train :	GAS
Descriptive Information :	Affected vehicles have been identified through production records.
Production Dates :	MAR 23, 2023 - JUN 15, 2023
VIN Range 1:1	Begin :WP1BA2AY1RDA49010End :WP1BA2AY5RDA50175Not sequential

# Part 573 Safety Recall Report

Vehicle Type : LIO Body Style : SU Power Train : GA	IV	
Descriptive Information : Af	fected vehicles have been identified through production records.	
Production Dates : MAY 04, 2023 - JUN 16, 2023 VIN Range 1 : Begin : WP1BK2AY2RDA72034 End : WP1BK2AY4RDA72486 Not sequentia		
Vehicle 5: 20	24-2024 Porsche Cayenne S Coupe	
Vehicle Type : LI		
Body Style : SU		
Power Train : GA		
-	fected vehicles have been identified through production records.	
	PR 12, 2023 - JUN 15, 2023 gin:WP1BL2AY8RDA60015 End:WP1BL2AY9RDA60475 🗌 Not sequential	
escription of Noncomplianc	e:	
Description of the	<b>e :</b> After the vehicle is shut off, the Gateway Control Unit is designed to shut off within approximately 5 minutes.	
Description of the	After the vehicle is shut off, the Gateway Control Unit is designed to shut off	
Description of the	After the vehicle is shut off, the Gateway Control Unit is designed to shut off within approximately 5 minutes. If the Hazard Warning Lights and/or Parking Lights are switched on within 10 seconds after the gateway control unit shut off, the rear hazard lamps or	
Description of the Noncompliance :	After the vehicle is shut off, the Gateway Control Unit is designed to shut off within approximately 5 minutes.If the Hazard Warning Lights and/or Parking Lights are switched on within 10 seconds after the gateway control unit shut off, the rear hazard lamps or parking lamps will not illuminate.The rear hazard warning lamps and parking lamps activate normally under any other circumstance.108 - Lamps, reflective devices, and assoc. Equipment	
Noncompliance : FMVSS 1 : FMVSS 2 :	After the vehicle is shut off, the Gateway Control Unit is designed to shut off within approximately 5 minutes.If the Hazard Warning Lights and/or Parking Lights are switched on within 10 seconds after the gateway control unit shut off, the rear hazard lamps or parking lamps will not illuminate.The rear hazard warning lamps and parking lamps activate normally under any other circumstance.108 - Lamps, reflective devices, and assoc. Equipment	
Description of the Noncompliance : FMVSS 1 : FMVSS 2 : Description of the Safety Risk :	After the vehicle is shut off, the Gateway Control Unit is designed to shut off within approximately 5 minutes. If the Hazard Warning Lights and/or Parking Lights are switched on within 10 seconds after the gateway control unit shut off, the rear hazard lamps or parking lamps will not illuminate. The rear hazard warning lamps and parking lamps activate normally under any other circumstance. 108 - Lamps, reflective devices, and assoc. Equipment NR If the rear Hazard Warning Lamps and / or rear parking lamps are not	

The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

Component Name 1:	Gateway control unit
Component Description :	As the central electronic control unit for managing a vehicle's data network, the gateway transmits and evaluates data between the vehicle networks and the various areas of the vehicle.
Component Part Number :	4KL907468L
1	Gateway control unit As the central electronic control unit for managing a vehicle's data network, the
1	с. С

#### **Supplier Identification :**

#### **Component Manufacturer**

Name: Lear Corporation Holding Spain SLU

Address : Calle Flusters, 54 Valls Foreign States 43800

Country: Spain

#### **Chronology**:

On July 20th, 2023, Porsche learned that, in certain specific circumstances, a software error in the gateway control unit may lead to an issue with Hazard Warning Signal activation. July 24th, 2023, Porsche`s Product Safety Committee determined that this issue was a noncompliance with FMVSS No. 108 and decided to recall the subject vehicles.

#### **Description of Remedy :**

<b>Description of Remedy Program :</b>	The gateway control unit will be reprogrammed.
	The owner's letter will not include a statement about customer
	reimbursement for pre-notification remedies as all of the affected vehicles are still covered under Porsche New Car Limited Warranty.
How Remedy Component Differs from Recalled Component :	The gateway control unit will be reprogrammed with a new data set.

The information contained in this report was submitted pursuant to 49 CFR §573

Identify How/When Recall Condition<br/>was Corrected in Production :Vehicles outside of the recall population will be equipped with updated<br/>Gateway Control Unit software.

#### **Recall Schedule :**

Description of Recall Schedule :Customers will be notified of this Recall by mail within 60 days of the<br/>filing of this report.Planned Dealer Notification Date :AUG 16, 2023 - AUG 16, 2023Planned Owner Notification Date :SEP 26, 2023 - SEP 26, 2023

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573