# Part 573 Safety Recall Report


Manufacturer Name :	Ford Motor Company			
Submission Date :	FEB 09, 2024			
<b>NHTSA Recall No. :</b>	24V-099			
Manufacturer Recall No. :	24S06			

#### Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

### Vehicle Information :

Vehicle 1:	2018-2020 Ford Expedit	tion		
Vehicle Type :	LIGHT VEHICLES			
Body Style :	ALL			
Power Train :	NR			
Descriptive Information :	Affected vehicles are equipped with driver and front passenger seatbelt retractor pretensioners and were built between October 01, 2018, and June 30, 2019. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. 3,101 2018 model year Ford Expedition vehicles are affected. 57,031 2019 model year Ford Expedition vehicles are affected. 23 2020 model year Ford Expedition vehicles are affected.			
Production Dates : OCT 01, 2018 - JUN 30, 2019				
VIN Range 1 : Begin :NREnd :NRInterpretation				





🖈 🛝 📩 😡

Number of potentially involved : 77,574

Estimated percentage with defect : 3%

**Population :** 

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

## **Part 573 Safety Recall Report**

24V-099

Vehicle 2:	2018-2020 Lincoln Navigator				
Vehicle Type :	LIGHT VEHICLES				
Body Style :					
Power Train :	NR				
Descriptive Information :	Affected vehicles are equipped with driver and front passenger seatbelt retractor pretensioners and were built between October 01, 2018, and June 30, 2019. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. 709 2018 model year Lincoln Navigator vehicles are affected. 16,696 2019 model year Lincoln Navigator vehicles are affected. 14 2020 model year Lincoln Navigator vehicles are affected.				
Production Dates :	OCT 01, 2018 - JUN 30, 2019				
VIN Range 1:	Begin :NREnd :NRNot sequentia				
escription of Defect :					
-	ect : On some of the affected vehicles, the driver and/or front passenger seatbelt retractor pretensioners may deploy inadvertently. The primary seatbelt locking functions continue to function properly.				
Description of the Defe	retractor pretensioners may deploy inadvertently. The primary seatbelt				
Description of the Defe FMVSS	retractor pretensioners may deploy inadvertently. The primary seatbelt locking functions continue to function properly.				
FMVSS	<ul> <li>retractor pretensioners may deploy inadvertently. The primary seatbelt locking functions continue to function properly.</li> <li>NR</li> <li>NR</li> <li>NR</li> </ul>				

and with a partial separation at the weld between the squib pin and the bridgewire (heating element of a pyrotechnic device), high resistance or open circuit may occur, and, if not resolved, may result in a retractor pretensioner inadvertent deployment. Increased humidity inside the cab, caused by water leakage after customer air-conditioning (A/C) usage in the hot temperature areas, may potentially contribute to the development of corrosion on top of the squib pins.

Identification of Any Warning An airbag malfunction light illuminates on the cluster preceding an inadvertent that can Occur : deployment of the seatbelt retractor pretensioner.

**Involved Components :** 

The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

24V-099

Page 3

Component Name 1:	Driver Seatbelt Retractor Pretensioner Assembly				
Component Description :	Driver Seatbelt Retractor Pretensioner Assembly for Ford Expedition				
Component Part Number :	JL1Z-78611B09-A*				
Component Name 2:	Front Passenger Seatbelt Retractor Pretensioner As				
Component Description :	Front Passenger Seatbelt Retractor Pretensioner Assembly for Ford Expedition				
Component Part Number :	JL1Z-78611B08-A*				
Component Name 3:	Driver Seatbelt Retractor Pretensioner Assembly				
•	Driver Seatbelt Retractor Pretensioner Assembly for Lincoln Navigator				
Component Part Number :					
Component Name 4	Front Dessenger Southalt Detrestor Drotonsion on As				
•	Front Passenger Seatbelt Retractor Pretensioner As				
	mponent Description : Front Passenger Seatbelt Retractor Pretensioner Assembly for Lincoln Navigator nponent Part Number : JL7Z-78611B08-A*				
Component Name 5 : Component Description : Component Part Number :	Drain Seal Tube - Elbow				
upplier Identification :					
Component Manufacturer					
Name : ZF					
Address: 4505 W. 26 Mile					
Washington Mic Country : United States	iiigaii 40034				
hronology :					

Chronology added as a separate attachment.

### **Description of Remedy :**

Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the production date codes inspected on both front seatbelt retractors. Dealers will replace any retractors that are within the suspect production date range. Additionally, dealers will inspect for the presence of a Heating Ventilation and Air-Conditioning (HVAC) drain tube elbow and install if not present. There will be no charge for this service. Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. The ending date for reimbursement eligibility is estimated to be March 31, 2025. Ford will forward a copy of the notification letters to dealers to the agency when available.
	Remedy pretensioner assemblies were built outside of the suspect time- window of the seatbelts that showed the propensity for inadvertent deployment.
dentify How/When Recall Condition was Corrected in Production :	1 1

#### **Recall Schedule :**

Description of Recall Schedule :	Notification to dealers is expected to occur on February 12, 2024. Mailing of owner notification letters is expected to begin March 04, 2024, and is expected to be completed by March 08, 2024.
Planned Dealer Notification Date :	FEB 12, 2024 - FEB 12, 2024
Planned Owner Notification Date :	MAR 04, 2024 <sup>-</sup> MAR 08, 2024

#### \* NR - Not Reported

0		ODI RES	SUME		
U.S. Department of Transportation <b>National Highway</b> <b>Traffic Safety</b> <b>Administration</b>	Investigation: Prompted By: Date Opened: Investigator: Approver: Subject:	VOQ Review	<b>Reviewer:</b> her Inadvertent De	Peter Kivett eployment	
MANUFACTURER & PRODUCT INFORMATION					
Manufacturer: Products: Population:	Ford Motor Comp 2019 Ford Exped 20,331 (Estimate	lition			
Problem Description:	•	pretensioner protection		hazardous condition from bility of moderate injury in	

FAILURE REPORT SUMMARY						
	ODI	Manufacturer	EWR D&I	Other	Total	EWR Field Reports
All Incidents:	10	0	0	0	10	0
Crashes/Fires:	0	0	0	0	0	0
Injury Incidents:	1	0	0	0	1	0
Number of Injuries:	1	0	0	0	1	0
Fatality Incidents:	0	0	0	0	0	0
Number of Fatalities:	0	0	0	0	0	0

#### ACTION/SUMMARY INFORMATION

Action: Open this Preliminary Evaluation (PE)

#### Summary:

The Office of Defects Investigation (ODI) has received 10 complaints alleging seat belt pretensioner inadvertent deployment in model year 2019 Ford Expedition vehicles manufactured by Ford Motor Company. Some complaints allege hearing a loud, explosion-like sound immediately followed by the seatbelt tightening around the occupant's torso area. The complaints also allege a burning smell and smoke filling the cabin of

the vehicle after the incident. The complaints do not allege a crash occurred that may have resulted in the deployment of the pretensioner system. Seat belt pretensioner replacement is required after deployment to restore functionality.

ODI is opening this Preliminary Evaluation (PE) to determine the scope and severity of the potential problem and to fully assess the potential safety-related problems. To review the ODI reports cited in the Opening Resume ODI Report Identification Number document, go to NHTSA.gov.