Part 573 Safety Recall Report

Manufacturer Name :Ford Motor CompanySubmission Date :0CT 15, 2021NHTSA Recall No. :21V-811Manufacturer Recall No. :21C25

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Population :

Number of potentially involved : 47,683 Estimated percentage with defect : 1 %

Vehicle Information :

Vehicle 1: 2	019-2021 Ford Ranger	
Vehicle Type : L	IGHT VEHICLES	
Body Style : P	ICKUP TRUCK	
Power Train : N	R	
	ffected vehicles are of the Super Cab body style. The Crew Cab body style uses a ifferent seatbelt assembly.	
2	he front passenger outboard seatbelt assemblies on vehicles built between June 17, 019 and August 4, 2021 may have seatbelt webbing routed only through the rubber rim sleeve, and not properly routed through the anchor.	
tl li sj	hese vehicles are not produced in VIN order. Information as to the applicability of nis action to specific vehicles can best be obtained by either calling Ford's toll-free ne (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain pecific information regarding the vehicles from the Ford On-line Automotive Service nformation System (OASIS) database.	
Production Dates : J	JN 17, 2019 - AUG 04, 2021	
VIN Range 1: Be		
Description of Noncompliance :		
-	The front passenger outboard seatbelt webbing may only be routed through the rubber trim sleeve, and not properly routed through the anchor eyelet.	
FMVSS 1	208 - Occupant crash protection	
	209 - Seat belt assemblies	
Description of the Safety Risk	: An improperly assembled seatbelt may not adequately restrain an occupant in a crash, increasing the risk of injury.	
Description of the Cause	: The seatbelt supplier's assembly process allowed for misrouting of the seatbelt	
The info	rmation contained in this report was submitted pursuant to 49 CFR §573	



21V-811

Part 573 Safety Recall Report

webbing, and the supplier's seat belt load test intended to verify proper routing had insufficient force to identify improperly routed seatbelts.

Identification of Any Warning None that can Occur :

Involved Components :

Component Name 1:S/BELT FRT/SEAT RETRComponent Description :RH Front Outboard Seatbelt AssemblyComponent Part Number :KB3B-21612D64-AL

Supplier Identification :

Component Manufacturer

Name : ZF Passive Safety US Inc.

Address : Avenida Pedregal No. 221 Reynosa Foreign States 88787 Country : Mexico

Chronology:

Chronology is provided as an attachment

Description of Remedy :

Description of Remedy Program :	Remedy is provided as an attachment
	Front seatbelt assemblies starting August 4, 2021 were inspected at the seatbelt assembly plant and warehouse to ensure the seatbelt webbing is properly routed through the rubber trim sleeve and the anchor's eyelet. On August 12, 2021, an additional control was instituted at the supplier to better align the rubber trim sleeve and the eyelet, additional sensors were added to confirm the alignment of the rubber trim sleeve hole and eyelet and the seatbelt load test was updated to a higher load to ensure a misrouted seatbelt would be identified.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 3

	Front seatbelt assemblies used on vehicles built starting August 4, 2021 were inspected at the vehicle assembly plant to ensure the seatbelt webbing is properly routed through the rubber trim sleeve and the anchor's eyelet. On August 12, 2021, an additional control was instituted at the supplier to better align the rubber trim sleeve and the eyelet, additional sensors were added to confirm the alignment of the rubber trim sleeve hole and eyelet and the seat belt load test was updated to a higher load to ensure a misrouted seatbelt would be identified.
Recall Schedule :	
	Notification to dealers is expected to occur on October 18, 2021. Mailing of owner notification letters is expected to begin November 15, 2021, and is expected to be completed by November 19, 2021.
Planned Dealer Notification Date :	
Planned Owner Notification Date :	NOV 15, 2021 - NOV 19, 2021

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573