| Manufacturer Name : | Ford Motor Company |
|---------------------------|--------------------|
| Submission Date : | APR 12, 2024 |
| NHTSA Recall No. : | 24V-267 |
| Manufacturer Recall No. : | 24S24 |
| | |

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Vehicle Information :

| Vehicle 1: | 2021-2024 Ford Bronco Sport | |
|--|---|--|
| | LIGHT VEHICLES | |
| Body Style : | ALL | |
| Power Train : | GAS | |
| Descriptive Information : | GAS Ford's team reviewed manufacturing records to determine the population of affected vehicles. The Ford process is capable of tracing Powertrain Control Module and Body Control Module calibrations to the vehicle in which the calibrations are installed. These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database. 402,978 Ford Bronco Sport vehicles are affected. | |
| Production Dates : FEB 05, 2020 - MAR 13, 2024 | | |
| VIN Range 1: | Begin :NREnd :NRNot sequential | |
| | | |



Number of potentially involved : 456,565

Estimated percentage with defect : 100 %

Population :

24V-267

24V-267

| Vehicle 2: 20 | 22-2023 Ford Maverick | |
|---|--|--|
| Vehicle Type : LI | GHT VEHICLES | |
| Body Style : AL | | |
| Power Train : NF | 2 | |
| Power Train :NRDescriptive Information :Ford's team reviewed manufacturing records to determine the population of affected vehicles. The Ford process is capable of tracing Powertrain Control Module and Body Control Module calibrations to the vehicle in which the calibrations are installed.These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.53,587 Ford Maverick vehicles are affected. | | |
| | | |
| Production Dates : FE | CB 03, 2021 - OCT 28, 2022 | |
| VIN Range 1 : Beg | gin: NR End: NR 🗌 Not sequential | |
| Description of Defect : Description of the Defect : | An insufficient calibration strategy for detecting sudden battery degradations during a drive cycle can lead to (a) a vehicle that is unable to restart after an auto start/stop event or (b) experience a stall while coming to a stop at low speed. Either may be accompanied by a loss of 12-volt accessories, including hazard lights. | |
| FMVSS 1 : | | |
| FMVSS 1 : FMVSS 2 : | | |
| FMVSS 2 :NRDescription of the Safety Risk :A loss of motive power can increase the risk of a crash.Description of the Cause :The BCM and PCM calibrations are unable to detect a sudden change in the 12- volt battery State of Charge (SOC) during a drive cycle.Identification of Any Warning that can Occur :None | | |
| Involved Components : | | |
| Component Name 1 : Body Control Module | | |
| Component Description : Body Control Module Calibration – Bronco Sport | | |

Component Part Number : M1PT-14F390-AC*

The information contained in this report was submitted pursuant to 49 CFR §573

24V-267

7 Page 3

| Component Name 2: | Body Control Module |
|-------------------------|--|
| Component Description : | Body Control Module Calibration – Maverick Gas |
| Component Part Number : | NZ6T-14F390-AD* |
| Component Name 3 : | Body Control Module |
| - | Body Control Module Calibration – Maverick HEV |
| Component Part Number : | |
| | |
| Component Name 4 : | Powertrain Control Module |
| 1 1 | Powertrain Control Module Calibration – MY2021 |
| Component Part Number : | M1PA-12A650-* |
| Component Name 5: | Powertrain Control Module |
| • | Powertrain Control Module Calibration – MY2022 |
| Component Part Number : | |
| | |
| Component Name 6 : | Powertrain Control Module |
| Component Description : | Powertrain Control Module Calibration – MY2023 |
| Component Part Number : | P1PA-12A650-* |
| Component Name 7: | Powertrain Control Module |
| • | Powertrain Control Module Calibration – MY2024 |
| Component Part Number : | |
| | |
| pplier Identification : | |
| Component Manufacturer | |
| Name : Ford Motor Com | pany |
| Address : 1 American Rd | |
| | an 48166 |

Country: United States

Chronology :

On October 25, 2023, The National Highway Traffic Safety Administration's Office of Defects Investigation (NHTSA ODI) requested information regarding allegations of loss of motive power (LOMP) followed by a loss of 12-volt accessories on 2021 MY Bronco Sport vehicles. NHTSA provided 29 potentially responsive Vehicle Owner Questionnaires (VOQs) that indicated that most customers' concerns were resolved with a 12-volt battery replacement.

On November 28, 2023, Ford's Critical Concern Review Group (CCRG) opened an investigation into this concern.

From November 2023 through January 2024, the Low Voltage Power Supply Engineering team evaluated field returns and warranty data for 2021 Bronco Sport vehicles focusing on 12-volt batteries and low voltage systems.

From December 2023 through March 2024, the Low Voltage Power Supply Engineering team conducted system and vehicle level testing and teardowns with batteries with various physical conditions and state of charge. The testing revealed that the Body Control Module (BCM) and Powertrain Control Module (PCM) calibrations are unable to detect the battery failure on these vehicles, which can result in a LOMP if the alternator is unable to keep up with the electrical load demand or if an Auto Stop-Start event is initiated.

On January 31, 2024, NHTSA's ODI opened Preliminary Investigation PE24-002 into this concern.

As of February 8, 2024, Ford is aware of 917 warranty reports, 11 field reports, and 54 customer complaints related to this concern. There are 3 unverified reports of fire and 2 property damage claims.

As of February 8, 2024, Ford is not aware of any accidents or injuries attributed to this condition.

On April 5, 2024 Ford's Field Review Committee reviewed the concern and approved a field action.

Description of Remedy :

| Description of Remedy Program : | Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the BCM and PCM calibrations updated. There will be no charge for this service. |
|---------------------------------|---|
| | Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. The ending date for reimbursement eligibility is estimated to be July 1, 2024. |

The information contained in this report was submitted pursuant to 49 CFR §573

Page 5

| [| | | |
|---|--|--|--|
| J 1 | The update BCM calibrations M1PT-14F390-ACG (Bronco Sport), NZ6T-14F390-ADD (Maverick Gas), NZ6T-14F390-BDB (Maverick HEV) will provide improved detection of 12V battery SOC during drive cycles, inhbit auto stop/start in the event of a low SOC, and provide notification to the driver if the battery is degraded. The updated PCM calibrations M1PA-12A650-UE (MY21), N1PA-12A650-AE (MY22), P1PA-12A650-AF (MY23), R1PA-12A650-AD (MY24) will increase the alternator output threshold to maintain vehicle operation if a low 12V battery SOC is detected during a drive cycle. | | |
| Identify How/When Recall Condition was Corrected in Production : | Not required per 49 Part 573. | | |
| | | | |
| Recall Schedule : | | | |
| Description of Recall Schedule : | Notification to dealers is expected to occur on May 13, 2024. Mailing of owner notification letters is expected to begin May 13, 2024 and is expected to be completed by May 17, 2024. | | |

Planned Dealer Notification Date : MAY 13, 2024 - MAY 13, 2024 Planned Owner Notification Date : MAY 13, 2024 - MAY 17, 2024

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573