# Part 573 Safety Recall Report

Ford Motor Company
NOV 09, 2023
23V-758
23S59

## Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

### Vehicle Information :

Vehicle 1:	2022-2023 Ford F-Super	Duty: F-350, F-450, F-550, F-	600
Vehicle Type :	BUSES, MEDIUM & HEAVY	Y VEHICLES	
Body Style :	ALL		
Power Train :	NR		
Descriptive Information :	population of affected par extender production to th Ford is able to provide the	e vehicle in which the front v e specific VIN list of affected pped with dual rear wheels (	ble of tracing front wheel hub wheel hub extender is installed. vehicles; see attachment VINs.
Production Dates :	DEC 08, 2022 - AUG 31, 20	)23	
VIN Range 1:	Begin : NR	End: NR	□ Not sequential
<b>Description of Defect :</b>	et . Affected vehicles are a	quipped with front wheel he	b ovtendor rotaining nute

Description of the Defect :	Affected vehicles are equipped with front wheel hub extender retaining nuts that may be insufficiently tightened. Insufficiently tightened front wheel hub extender retaining nuts may result in separation of the wheel and wheel extender from the vehicle.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Insufficiently tightened front wheel hub extender retaining nuts may result in front wheel and wheel extender detachment from the vehicle, increasing the risk of a crash. A wheel assembly that separates from a vehicle while driving may create a road hazard, increasing the risk of injury or crash.
Lhe infor	mation contained in this report was submitted pursuant to 49 CFR §573

## NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

### **Population :**

Number of potentially involved :13Estimated percentage with defect :100 %

🖈 🛝 📩 😡

23V-758

The information contained in this report was submitted pursuant to 49 CFR §573

<b>Part 573 S</b>	Safety Recal	l Report
-------------------	--------------	----------

Page 2
--------

Description of the caus	e: Due to a process error during equipment faults at the supplier's manufacturing facility, the automated torque station for tightening the front wheel hub extender retaining nuts allowed prior torque data to be written to a front wheel hub extender assembly in certain limited instances.
	ng Front wheel hub extender retaining nuts that are loose may lead to vibration r: and noise while driving.
olved Components :	
Component Name 1 :	Front Axle
Component Description :	F-350 Front Axle - Dual Rear Wheel 3.55 Gear Ratio 4x4
Component Part Number :	PC34-3002-TD
Component Name 2 :	Front Axle
-	F-350 Front Axle - Dual Rear Wheel 3.73 Gear Ratio 4x4
Component Part Number :	PC34-3002-DD
Component Name 3 :	Front Ayle
-	F-350 Front Axle - Dual Rear Wheel 4.10 Gear Ratio 4x4
Component Part Number :	
Component Name 4:	Front Axle
-	F-450 / F-550 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4
Component Part Number :	
Component Name 5:	Front Axle
<b>Component Description :</b>	F-450 / F-550 Front Axle - Dual Rear Wheel 4.30 Gear Ratio 4x4
Component Part Number :	PC34-3002-VE

The information contained in this report was submitted pursuant to 49 CFR \$573

# Part 573 Safety Recall Report

23V-758

Page 3

Component Description : Component Part Number :F-600 Front Axle - Dual Rear Wheel 4.30 Gear Ratio 4x4Component Name 7 : Component Description :Front AxleF-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4Component Part Number :F-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4	Component Name 6:	Front Axle
Component Name 7: Front Axle Component Description: F-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4	Component Description :	F-600 Front Axle - Dual Rear Wheel 4.30 Gear Ratio 4x4
Component Description : F-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4	Component Part Number :	PC34-3002-XE
Component Description : F-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4		
	Component Name 7:	Front Axle
Component Part Number : PC34-3002-ZE	Component Description :	F-600 Front Axle - Dual Rear Wheel 4.88 Gear Ratio 4x4
	Component Part Number :	PC34-3002-ZE
Component Name 8 : Front Axle	Component Name 8:	Front Axle
Component Description : F-450 / F-550 Front Axle - Dual Rear Wheel 4x2 Chassis Cab	Component Description :	F-450 / F-550 Front Axle - Dual Rear Wheel 4x2 Chassis Cab
Component Part Number : PC34-3001-CD	Component Part Number :	PC34-3001-CD

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Dana Incorporated Address : 3939 Technology Drive Maumee Ohio 43537 Country : United States

#### **Chronology**:

On October 19, 2023, Ford's Critical Concern Review Group (CCRG) initiated an investigation into a field report of a wheel and wheel hub extender detachment on a 2023 Ford Super Duty vehicle during a low-speed maneuver. The field report indicated vehicle vibration prior to the wheel and wheel extender detachment and no injuries were reported.

Ford conducted a review of the axle supplier's assembly processes and production records and identified a concern at the supplier's manufacturing facility. The review of supplier records identified axles that may contain insufficiently torqued wheel extender retaining nuts. If certain assembly equipment faults or malfunctions during manufacturing, torque data for a previously assembled front wheel hub extender can be erroneously recorded for a front wheel hub extender currently in the retaining nut torquing station without performing the torque operation. Ford identified the specific instances when this occurred, and can trace suspect wheel hub extenders by axle serial number to specific vehicle VINS.

As of November 01, 2023, Ford is aware of one (1) field report received on October 16, 2023, related to this

The information contained in this report was submitted pursuant to 49 CFR §573

concern.

On November 03, 2023, Ford's Field Review Committee reviewed the concern and approved a field action.

Ford is not aware of any reports of injury related to this condition.

#### **Description of Remedy :**

Description of Remedy Program :	Ford is contacting owners and instructing them to not drive their vehicle. Owners are asked to work with a Ford or Lincoln dealer to have their vehicle towed in for service. Dealers will inspect the front wheel hub extender retaining nuts. If a front wheel hub extender retaining nut is found to be loose, the dealer will replace the wheel hub extender, retaining nuts, and hub assembly. There will be no charge for this service.
	Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in May 2023. The ending date for reimbursement eligibility is estimated to be December 15, 2023.
	Ford will forward a copy of the notification letters to dealers to the agency when available.
How Remedy Component Differs from Recalled Component :	Front wheel hub extender retaining nuts will be torqued to specification.
Identify How/When Recall Condition was Corrected in Production :	Not required per 49 Part 573.

#### **Recall Schedule :**

Description of Recall Schedule :	Notification to dealers occurred on November 06, 2023. Ford is currently contacting owners by phone and email. Mailing of owner notification letters is expected to begin November 27, 2023, and is expected to be completed by December 01, 2023.
Planned Dealer Notification Date :	NOV 09, 2023 - NOV 09, 2023
Planned Owner Notification Date :	NOV 27, 2023 - DEC 01, 2023

#### \* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573