# Part 573 Safety Recall Report

Manufacturer Name :General Motors, LLCSubmission Date :JUN 23, 2022NHTSA Recall No. :22V-446Manufacturer Recall No. :N222366070

### Manufacturer Information :

Manufacturer Name : General Motors, LLC

Address : 29427 Louis Chevrolet Road MAIL CODE 480-210-2V WARREN MI 48093 Company phone : 586-596-1733

### Vehicle Information :

Vehicle 1:	2022-2022 Ca	dillac XT6			
Vehicle Type :					
Body Style :					
Power Train :	NR				
Descriptive Information :	<ul> <li>Manufacturing records were used to determine the affected population.</li> <li>This recall involves only all-wheel drive (AWD) models. Front-wheel drive (FWD) models are not affected. Vehicles produced with fuel tanks outside of GM's suspect window and vehicles addressed prior to shipment are not included in this recall.</li> <li>There are 29 Cadillac XT6 vehicles included in this recall.</li> </ul>				
Production Dates :	MAR 16, 2022	2 - MAR 21, 20	22		
VIN Range 1:		NR	End: NR	Not sequential	
Vehicle 2:	2022-2022 GN	MC Acadia			
Vehicle Type :					
Body Style :					
Power Train :	NR				
Descriptive Information :	Manufacturing records were used to determine the affected population.				
	This recall involves only all-wheel drive (AWD) models. Front-wheel drive (FWD) models are not affected. Vehicles produced with fuel tanks outside of GM's suspect window and vehicles addressed prior to shipment are not included in this recall. There are 135 GMC Acadia vehicles included in this recall.				
			99		
Production Dates :	MAR 16, 2022	: - MAR 21, 20	66		



Number of potentially involved : 228 Estimated percentage with defect : 4 %

**Population :** 

22V-446

## Part 573 Safety Recall Report

	2022-2022	Cadillac XT5		
Vehicle Type : Body Style :				
Power Train :				
Descriptive Information :	Manufactur	ring records w	ere used to determine the a	ffected population.
	models are	not affected.		els. Front-wheel drive (FWD) tanks outside of GM's suspect e not included in this recall.
	There are 6	64 Cadillac XT5	ovehicles included in this re	call.
Production Dates :	MAR 16, 20	)22 - MAR 21, 2	2022	
VIN Range 1: I	Begin :	NR	End: NR	☐ Not sequential
FMVSS FMVSS Description of the Safety Ris	2 : NR k : If the fu certain	types of rollov	er crashes. If a rollover cras	leak from the vehicle during sh were to occur, and if fuel is an increased risk of post-
Description of the Caus	connect	erforming a pr ion internal to	cocedure to evaluate the inte the tank, operators in GM's ed a portion of the rollover v	assembly plant may have
Identification of Any Warni that can Occu	ng NR			5
nvolved Components :				
Component Name 1	TANK ASI	M-FUEL		

The information contained in this report was submitted pursuant to 49 CFR §573

#### **Supplier Identification :**

**Component Manufacturer** 

Name : NR Address : NR NR Country : NR

#### **Chronology**:

On March 22, 2022, a worker at GM's Spring Hill assembly plant submitted an issue to GM's Speak Up For Safety (SUFS) program following discovery of a dislodged fuel tank rollover valve in a vehicle. Personnel at the plant determined that the issue was caused while performing a procedure to evaluate the integrity of a fuel pump connection inside the tank. Containment efforts were initiated at the plant, and 31 of the 708 contained vehicles were found to have the dislodged-valve condition.

GM opened a formal investigation on May 10, 2022. GM's investigator confirmed that 298 vehicles may have been shipped from GM's assembly plant with this condition, of which 228 are in the US. Between June 6 and 8, 2020, GM conducted laboratory tests to assess this condition's potential to cause a fuel leak in various roll positions. GM determined that, when left in certain roll positions for an extended period of time (approximately 17 minutes), a dislodged valve could allow fluid to leak. GM's review of field data did not identify any relevant field claims related to this condition. On June 16, 2022, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall.

#### **Description of Remedy :**

Description of Remedy Program :	Dealers will inspect the fuel tank and replace the fuel tank shell if the rollover valve is found to be dislodged or missing. Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under warranty, so reimbursement is not offered.
How Remedy Component Differs from Recalled Component :	Fuel tank rollover valves are not dislodged.
5	Containment efforts were initiated on March 21, 2022. Vehicles produced after this date were not subject to the same fuel pump connect check procedure or were inspected and addressed prior to shipment.

#### **Recall Schedule :**

Description of Recall Schedule : Dealers will be notified on June 23, 2022. GM estimates owner notification will begin on August 8, 2022.

## Part 573 Safety Recall Report

22V-446

Planned Dealer Notification Date :JUN 23, 2022 - JUN 23, 2022Planned Owner Notification Date :AUG 08, 2022 - AUG 08, 2022

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573