OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-087

Manufacturer Name: General Motors, LLC

Submission Date: FEB 08, 2024 NHTSA Recall No.: 24V-087 Manufacturer Recall No.: N242430730



Manufacturer Information:

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

Population:

Number of potentially involved: 352 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2024-2024 Chevrolet Silverado EV

Vehicle Type: **Body Style:** Power Train: NR

Descriptive Information : Manufacturing records were used to determine the affected population.

Production Dates: FEB 23, 2023 - NOV 14, 2023

VIN Range 1: Begin: NR End: NR Not sequential

Description of Defect:

Description of the Defect: General Motors has decided that a defect which relates to motor vehicle safety

exists in certain 2024 model year Chevrolet Silverado EV vehicles. An incorrect seat belt bezel installed at the second-row center seating position may damage

or tear the seat belt in certain crash conditions.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the second-row center seat belt tears during a crash, an occupant in that

seating position may not be properly restrained, increasing the risk of injury.

Description of the Cause: An incorrect rear seat bezel was installed.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: BEZEL-R/SEAT BELT OPG

Component Description: Second-row center seat belt bezel

Component Part Number: 84034259

Supplier Identification:

Component Manufacturer

Name: NR

Address: NR

NR

Country: NR

Chronology:

On November 13, 2023, a GM engineer submitted an issue to GM's Speak Up For Safety (SUFS) program after discovering that incorrect seat belt bezels were distributed to the assembly line which installs this part on the Silverado EV. GM opened a product investigation on November 28, 2023.

GM's investigation determined that 352 Silverado EV vehicles built between February 23, 2023 and November 14, 2023 may have been built with an incorrect bezel. Sled tests with the incorrect bezel installed at the rear center seat location showed that under heavy loading (95th percentile male test dummy in a 35-mph frontal impact) bunching of the belt at the bezel opening may damage or tear the belt.

On February 1, 2024, GM's Safety Field Action Decision Authority (SFADA) decided to conduct a safety recall. GM is not aware of any field incidents or injuries associated with this defect.

Description of Remedy:

Description of Remedy Program: Dealers will replace the second-row center seat belt bezel with the correct

bezel. Pursuant to 577.11, General Motors does not plan to provide notice about reimbursement to owners because owners would not have been

aware of the issue prior to this recall.

How Remedy Component Differs The correct bezel is designed to disengage under heavy loads to prevent

from Recalled Component: bunching of the seat belt.

Identify How/When Recall Condition Containment was implemented at GM's assembly plant on November 13,

was Corrected in Production: 2023.

Recall Schedule:

Description of Recall Schedule: Containment was implemented at GM's assembly plant on November 13,

2023.

Planned Dealer Notification Date : FEB 08, 2024 - FEB 08, 2024 Planned Owner Notification Date : MAR 25, 2024 - MAR 25, 2024

* NR - Not Reported