Part 573 Safety Recall Report

Manufacturer Name :Honda (American Honda Motor Co.)Submission Date :NOV 23, 2022NHTSA Recall No. :22V-867Manufacturer Recall No. :6RW



22V-867

Manufacturer Information :

Manufacturer Name : Honda (American Honda Motor Co.) Address : 1919 Torrance Blvd. Torrance CA 90501 Company phone : 1-888-234-2138

Population :

Number of potentially involved : 117,445 Estimated percentage with defect : 7 %

Vehicle Information :

Vehicle 1:	2017-2019 Honda Ridgelin	e	
Vehicle Type :	LIGHT VEHICLES		
Body Style :	PICKUP TRUCK		
Power Train :	GAS		
Descriptive Information :	The recall population was determined based on supplier and manufacturing records. The production range reflects all possible vehicles that could experience the problem.		
Production Dates :	OCT 29, 2015 - JUN 01, 201	9	
VIN Range 1:	Begin : NR	End: NR	☐ Not sequential

Description of Defect :

Description of the Defect :	The rear-view camera (RVC) tailgate wire harness may fatigue and break after repeated opening and closing of the tailgate.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A broken wire harness may result in a failure to display the RVC image, which may affect the driver's view and increase the risk of a back-up collision or injury.
Description of the Cause :	The RVC wire harness was manufactured with a protective corrugated tubing and harness guide to help protect the wiring from stress when the tailgate was opened and closed; a zip tie was used to keep the corrugated tubing and guide in the proper position. With some RVC wire harnesses, the length of corrugated tubing inserted into the harness guide (i.e., the overlap between the corrugated tubing and the harness guide) was insufficient to provide optimal protection and the zip tie was insufficiently tightened to keep the tubing and guide in the proper position.
Identification of Any Warning that can Occur :	NR

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Involved Components :

Component Name 1 : WIRE HARN, TAILGATE Component Description : TAILGATE WIRE HARNESS Component Part Number : 32109-T6Z-A000

Supplier Identification :

Component Manufacturer

Name : APTIV US LCC Address : 5725 Innovation Drive Troy Michigan 48098 Country : United States

Chronology:

July 19, 2018

Honda observed a potential trend of, and received a market quality report on, malfunctioning RVCs in affected vehicles from North America.

October 2018 – November 2019

Honda investigated the issue to determine potential causes and prevalence of the issue in the market. Honda's investigation identified that variations in the tightness of the zip tie holding the protective corrugated tubing in place and the depth to which the corrugated tubing was inserted into the associated harness guide could impact RVC performance. During this time, Honda applied production improvements to address these potential variations, with the last being applied on June 3, 2019.

November 2019 – July 2021 Honda continued to monitor the issue.

July 2021 – August 2021 Honda received communication from NHTSA ODI to investigate reports of RVC malfunctions in the affected vehicles. Honda informed NHTSA the concern was currently under study.

February 2022 – April 2022 NHTSA ODI opened a Preliminary Evaluation (PE) defect investigation. Honda informed NHTSA that the issue was considered to be one of quality, unrelated to safety.

October 27, 2022 NHTSA ODI notified Honda that the issue was considered to be related to safety.

The information contained in this report was submitted pursuant to 49 CFR §573

22V-867

November 17, 2022

Honda determined that a defect related to motor vehicle safety existed and decided to conduct a safety recall.

As of November 17, 2022, Honda has received 3,437 warranty claims related to the issue between December 2017 to October 2022, and no reports of injuries or deaths related to this issue.

Description of Remedy :

Description of Remedy Program :	asked to take their vehicle to an authorized Honda dealer. The dealer will replace the rear-view camera tailgate harness with an improved part.	
	Owners who have paid to have these repairs completed at their own expense will be eligible for reimbursement, in accord with the recall reimbursement plan on file with NHTSA.	
	Recalled components may contain an insufficiently tightened zip tie and corrugated tubing that is not inserted sufficiently far into the harness guide.	
Identify How/When Recall Condition was Corrected in Production :	The harness assembly and inspection process have been improved.	

Recall Schedule :

Description of Recall Schedule :	Dealer notification is scheduled to begin and end on or about $11/23/2022$. Owner notification is scheduled to begin on and end on or about $1/16/2023$.
Planned Dealer Notification Date :	NOV 23, 2022 - NOV 23, 2022
Planned Owner Notification Date :	JAN 16, 2023 - JAN 16, 2023

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573