Part 573 Safety Recall Report

Manufacturer Name :Isuzu Technical Center of America, Inc.Submission Date :MAY 20, 2022NHTSA Recall No. :22V-362Manufacturer Recall No. :V2201

Manufacturer Information :

Manufacturer Name :Isuzu Technical Center of America, Inc.Number of potentially involved :154Address :46401 Commerce Center Drive
Plymouth MI 48170-2473Estimated percentage with defect :100 %Company phone :866-441-9638100 %

Population :

Vehicle Information :

Vehicle 1:	2022-2022 ISUZU FTR	
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :	OTHER	
Power Train :	DIESEL	
Descriptive Information :	This recall applies to all MY 2022 Isuzu F-series trucks (with a Cummins diesel engine) built before 2/1/2022. [144 vehicles]	
	[VIN 8: "F" Cummins Engine] No Chevrolet LCF (6500XD/7500XD) trucks are involved in this recall.	
Production Dates :	OCT 07, 2021 - JAN 31, 2022	
VIN Range 1 : Begin : 54DK6S1F1NSA50017 End : 54DK6S1F1NSA70039 🗸 Not sequential		
	2022-2022 ISUZU FVR	
• •	BUSES, MEDIUM & HEAVY VEHICLES	
Body Style :		
Power Train :	DIESEL	
Descriptive Information :	This recall applies to all MY 2022 Isuzu F-series trucks (with a Cummins diesel engine) built before 2/1/2022. [10 Vehicles] [VIN 8: "F" Cummins Engine] No Chevrolet LCF (6500XD/7500XD) trucks are involved in this recall.	
Production Dates :	DEC 08, 2021 - JAN 25, 2022	
VIN Range 1: Begin: 54DM6S1F9NSB50259 End: 54DM6S1F9NSB50603 Not sequential		



22V-362

Page 2

Description of Defect :

Description of the Defect :	The quick connector used to connect fuel suction hose to the fuel inlet pipe of the engine was spec'd as Ø12.6 mm when it should have been Ø11.8 mm. Because of the larger diameter of the quick connector, the sealing performance at this connection point is inadequate, resulting in the possibility of diesel fuel leakage from the connection point during the manufacturing or servicing process. It is also possible that the gap may allow outside air to be sucked into the fuel hose while the engine is running.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Diesel fuel leakage in the presence of an ignition source potentially increases the risk of fire. Air intake into the fuel hose potentially increases the risk of engine stalling, which could lead to a crash.
Description of the Cause :	Incorrect design specification of the diameter of the quick connector.
5 0	The operator may notice engine crank delays, the engine failing to start, rough idling and/or possible illumination of the Check Engine Light.

Involved Components :

Component Name 1:	ASSEMBLY: FUEL HOSE
Component Description :	FUEL SUCTION HOSE TO ENGINE.
Component Part Number :	8976665721

Supplier Identification :

Component Manufacturer

Name: FLUID ROUTING SOLUTIONS

Address: 1921 N. Broad Street

Lexington Tennessee 38351

Country : United States

Chronology :

Separately uploaded.

The information contained in this report was submitted pursuant to 49 CFR \$573

Description of Remedy :				
Description of Remedy Program :	Isuzu dealers will replace the quick connector with a different quick connector of the correct size (Ø11.8 mm). Parts are under warranty.			
How Remedy Component Differs from Recalled Component :	Remedy component: The quick connector is Ø11.8 mm w/ blue connector lock Recalled component: The quick connector is Ø12.6 mm w/ red connector lock			
Identify How/When Recall Condition was Corrected in Production :	Trucks built in production on or after April 18, 2022 have the correct size quick connector.			
Recall Schedule :				
Description of Recall Schedule : Planned Dealer Notification Date : Planned Owner Notification Date :				

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573