8

# Part 573 Safety Recall Report

Manufacturer Name :Kia America, Inc.Submission Date :APR 16, 2024NHTSA Recall No. :24V-271Manufacturer Recall No. :SC308

### Manufacturer Information :

Manufacturer Name : Kia America, Inc.

Address : 111 Peters Canyon Road Irvine CA 92606

Company phone : 800-333-4542

## Vehicle Information :

Vehicle 1:	2023-2023 Kia Niro EV		
Vehicle Type :	LIGHT VEHICLES		
Body Style :			
Power Train :	HYBRID ELECTRIC		
Descriptive Information :	Certain 2023 model year through May 16, 2023 (4)	Niro EV vehicles manufacture units).	d from November 7, 2022
	records. The vehicles sub	ject to this recall were not pro ation about their specific veh	
Production Dates :	NOV 07, 2022 - MAY 16, 2	023	
VIN Range 1:	Begin : NR	End: NR	☐ Not sequential
	2024-2024 Kia EV9		
01	LIGHT VEHICLES		
Body Style :			
Power Train :	HYBRID ELECTRIC		
Descriptive Information :	Certain 2024 model year December 14, 2023 (4 uni		om October 27, 2023 through
	records. The vehicles sub	ject to this recall were not pro ation about their specific veh	
Production Dates :	OCT 27, 2023 - DEC 14, 20	23	
VIN Range 1:		End: NR	□ Not sequential
	-		
The i	nformation contained in this re	port was submitted pursuant to 49	9 CFR §573



Number of potentially involved :

Estimated percentage with defect : 1%

**Population :** 

## 24V-271

## Part 573 Safety Recall Report

24V-271

Page 2

### **Description of Defect :**

Description of the Defect :	The differential gear bolts within the vehicle's Gear Drive Unit (GDU) may not have been properly torqued during the assembly by the differential gear supplier. Over time, the differential bolts within the GDU may loosen and damage the GDU housing and/or reduction gear while driving. Continued driving with a grinding noise from a damaged GDU housing or reduction gear may result in a loss of motive power and/or cause the differential to lock up.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A loss of motive power and/or differential lock up increases the risk of a crash.
Description of the Cause :	Improperly torqued differential gear bolts.
Identification of Any Warning that can Occur :	Grinding noise while driving.

#### **Involved Components :**

Component Name 1:	NIRO EV: MOTOR-GDU ASSY
Component Description :	Gear Drive Unit Assembly
Component Part Number :	36501-0EDA0

Component Name 2	: EV9: MOTOR-GEAR DRIVE UNIT ASSY, RR	

Component Description : Gear Drive Unit Assembly

Component Part Number : 44000-18MD0

#### **Supplier Identification :**

#### **Component Manufacturer**

Name :Hyundai TransysAddress :105 Sindang 1-ro, Seongyeon-myeon,<br/>Chungcheongnam-do Seosan-Si Foreign States 31930Country :Korea, Republic of

The information contained in this report was submitted pursuant to 49 CFR §573

## Part 573 Safety Recall Report

24V-271

### **Chronology** :

See attached document titled "2023MY Niro EV & 2024MY EV9 Gear Drive Unit (GDU) Chronology".

#### **Description of Remedy :**

Description of Remedy Program :	All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Kia dealer. Kia dealers will replace the Gear Drive Unit with a new one.
	Kia will reimburse owners for repair expenses already incurred pursuant to Kia's General Reimbursement Plan filed May 10, 2022.
How Remedy Component Differs from Recalled Component :	The differential gear bolts in the remedy component have been properly torqued.
	Niro EV vehicles manufactured beginning on $5/17/2023$ and EV9 vehicles manufactured beginning $12/15/2023$ are equipped with Gear Drive Units with properly torqued differential bolts

#### **Recall Schedule :**

Description of Recall Schedule :	The planned dealer notification begin and end date is April 19, 2024. The planned owner notification begin and end date is May 17, 2024.
Planned Dealer Notification Date :	APR 19, 2024 - APR 19, 2024
Planned Owner Notification Date :	MAY 17, 2024 - MAY 17, 2024

\* NR - Not Reported