# Part 573 Safety Recall Report

# Manufacturer Name :Hyundai Motor AmericaSubmission Date :FEB 23, 2024NHTSA Recall No. :24V-146Manufacturer Recall No. :256

### Manufacturer Information :

Manufacturer Name :Hyundai Motor AmericaAddress :10550 Talbert AvenueFountain Valley CA 92708Company phone :800-633-5151

## Vehicle Information :

Vahiala 1.	2015 2016 U	uundai Elant	<b>no</b>	
	2015-2016 H	0	ſď	
Vehicle Type :		LES		
Body Style :				
Power Train :				
Descriptive Information :	Based on manufacturing records, the affected vehicles include 135,074 model year 2015-2016 Hyundai Elantra vehicles produced within the specified production date range by Hyundai Motor Manufacturing Alabama ("HMMA") for sale in the U.S. market.			
Production Dates :	FEB 02, 2015	- DEC 22, 20	15	
VIN Range 1:	Begin :	NR	End: NR	☐ Not sequential
Vehicle Type : Body Style : Power Train :	4-DOOR GAS	LES		s include 51,514 model year
-	2015-2016 Hyundai Elantra vehicles produced within the specified production date range by Hyundai Motor Company ("HMC") for sale in the U.S. market.			
Production Dates :				
	Begin :	NR	End: NR	Not sequential

Description of the Noncompliance : Noncompliance : The trunk latch pawl in the subject vehicles can thermally contract when exposed to high ambient temperature. While engaged in this condition, any attempt to manually release the pawl to open the trunk could result in the pawl becoming damaged.

FMVSS 1: 401 - Internal trunk release

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 186,588 Estimated percentage with defect : 1%

**Population**:

## 24V-146

## Part 573 Safety Recall Report

Page 2

FMVSS 2 :	NR
Description of the Safety Risk :	A damaged pawl could prevent opening of the trunk lid through actuation of the emergency trunk release, which could increase the risk of injury to occupants. As such, the involved vehicles might not comply with Federal Motor Vehicle Safety Standard No. 401, "Interior Trunk Release."
Description of the Cause :	The pawl material is insufficient at withstanding environmental conditions involving high ambient temperature.
Identification of Any Warning that can Occur :	The trunk lid may require increased effort to open from the latched position.
nvolved Components :	
-	LATCH ASSY-TRUNK LID
Component Name 1 : I	LATCH ASSY-TRUNK LID Frunk latch assembly (standard key release)
	Frunk latch assembly (standard key release)
Component Name 1 : I Component Description : 7 Component Part Number : 8	Frunk latch assembly (standard key release)
Component Name 1 : I Component Description : 7 Component Part Number : 8 Component Name 2 : I	Frunk latch assembly (standard key release) 31230-3X000

#### **Supplier Identification :**

#### **Component Manufacturer**

Name :Daedong Hi-Lex INCAddress :43, Namdongdong-ro 78beon-gil<br/>Namdong-gu Incheon Foreign States 21692Country :Korea, Republic of

#### **Chronology**:

See Attachment A for the testing events leading to noncompliance decision.

The information contained in this report was submitted pursuant to 49 CFR \$573

#### **Description of Remedy :**

Description of Remedy Program :	All owners of the subject vehicles will be notified by first class mail with instructions to bring their vehicles to a Hyundai dealer to have the trunk latch base sub-assembly replaced. This remedy will be offered at no cost to owners for all affected vehicles, regardless of whether the affected vehicles are still covered under Hyundai's New Vehicle Limited Warranty. Additionally, Hyundai will provide owners of affected vehicles reimbursement for out-of-pocket expenses incurred to obtain a remedy for the recall condition in accordance with the reimbursement plan submitted to NHTSA on February 24, 2022.
	The remedy trunk latch base pawl contains improved material increasing its resistance to thermal contraction.
Identify How/When Recall Condition was Corrected in Production :	

#### **Recall Schedule :**

Description of Recall Schedule :	Notifications will be mailed in accordance with the specified dates.
Planned Dealer Notification Date :	APR 15, 2024 - APR 15, 2024
Planned Owner Notification Date :	APR 15, 2024 - APR 15, 2024

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573