Part 573 Safety Recall Report

Manufacturer Name :Volkswagen Group of America, Inc.Submission Date :SEP 21, 2022NHTSA Recall No. :22V-707Manufacturer Recall No. :19Q8



Manufacturer Name :Volkswagen Group of America, Inc.Address :3800 Hamlin RoadAuburn Hills MI 483261-800-893-5298

Vehicle Information :

Vehicle 1 : 2 Vehicle Type :	2022-2023 VOLKSWAGEN GOLF R A8
Vehicle Type :	
· · · · · · · · · · · · · · · · · · ·	
Body Style :	
Power Train :	NR
- 	The recall population was determined by production records. The recalled products differ from products that were not included in the recall because during a specific time period, the radiator have may not have been sufficiently affixed to the intercooler in the potentially affected vehicles. GOLF R A8 count: 1406
Production Dates : 1	MAR 09, 2021 - JUL 14, 2022
VIN Range 1:B	Begin : WVWFB7CD9NW000160 End : WVWFB7CD5PW100128 ☑ Not sequential
Vehicle 2 : 2 Vehicle Type : Body Style : Power Train : 1	2022-2023 VOLKSWAGEN GOLF GTI NR
	The recall population was determined by production records. The recalled products differ from products that were not included in the recall because during a specific time period, the radiator have may not have been sufficiently affixed to the intercooler in the potentially affected vehicles. GOLF GTI count: 6632
Production Dates :	FEB 10, 2021 - JUL 20, 2022
VIN Range 1 : Begin : WVW5A7CD5NW000137 End : WVWZZ7CD5PW100008	

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

Population :

22V-707

🔂 🔨 🖪

Number of potentially involved : 8,038 Estimated percentage with defect : 1 %

Description of Defect :

Description of the Defect :	During vehicle production, the radiator may not have been affixed correctly to the intercooler. This can result in the radiator becoming loose and causing a coolant hose to contact the V-belt pulley.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A coolant hose that contacts the V-belt pulley can become damaged, potentially resulting in a coolant leak. A large amount of coolant leaking onto the roadway may increase the risk of a crash for the following traffic. If the red warning light in the instrument cluster is ignored and the vehicle continues to be driven without coolant, the engine may overheat, potentially leading to a vehicle fire.
Description of the Cause :	During vehicle production, the radiator may not have been affixed correctly to the intercooler.
	If a low coolant level is detected, the driver will see a red warning light in the instrument cluster.

Involved Components :

Component Name 1:	Coolant hose
Component Description :	Coolant hose
Component Part Number :	5WA.122.051.AD (GTI)

Component Name 2 :	Coolant hose
Component Description :	Coolant hose
Component Part Number :	5WA.122.051.R (R-Golf)

Component Name 3 :	Poly V-belt
Component Description :	Poly V-belt
Component Part Number :	06L.903.137.A (GTI)

Component Name 4 :	Poly V-belt
Component Description :	Poly V-belt
Component Part Number :	06Q.903.137.A (R-Golf)

The information contained in this report was submitted pursuant to 49 CFR \$573

Supplier Identification :

Component Manufacturer

Name : Volkswagen AG Address : Berliner ring 2 Wolfsburg Country : Germany

Foreign States 38440

Chronology :

January 2021: The first field claims were received from countries outside of the USA. Analysis started. January 2021 - September 2021: In-depth analysis was conducted and a root cause was identified. Statistical analysis indicated failure as occurring very early in vehicle life. A red warning light in the instrument cluster warns the vehicle operator of a coolant leak and, if the warning is ignored, there is the potential for engine overheating. Ongoing field monitoring.

September 2021 - August 2022: Ongoing field monitoring. Review of field situation in the U.S. market. 09/09/2022: Topic presented in Volkswagen's Pre Product Safety committee. Further data regarding scope of potentially affected vehicles was requested.

09/14/2022: Topic was presented in Volkswagen's Product Safety Committee. Due to the recognizability if this condition is present, the risk for a potential engine overheat is seen as low. Out of abundance of caution, a recall was decided. The decision was based on 27 claims for potentially damaged coolant hoses that could be attributed to this topic in the U.S. market. These claims have a date range of June 2022-August 2022.

Description of Remedy :

Description of Remedy Program :	At no cost to customers, the affected vehicles will be inspected to see if the radiator is correctly affixed to the intercooler. If a loose connection is found, the coolant hose and the poly V-belt will be checked for damage. If damage is found, the damaged parts will be replaced. Volkswagen will not offer a reimbursement plan under this recall.
	The remedy component and the recalled component are identical. Assembly topic only. The vehicles that were not recalled have been manufactured with a properly connected radiator.
Identify How/When Recall Condition was Corrected in Production :	CW27/2022 Improved process to affix radiator to intercooler at a seperate assembly step.

Recall Schedule :

Description of Recall Schedule :	Dealers/owners: on or before November 18, 2022
Planned Dealer Notification Date :	NOV 18, 2022 - NOV 18, 2022
Planned Owner Notification Date :	NOV 18, 2022 - NOV 18, 2022

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573