Part 573 Safety Recall Report

Manufacturer Name :	Kia America, Inc.
Submission Date :	SEP 15, 2023
NHTSA Recall No. :	23V-639
Manufacturer Recall No. :	SC282

Manufacturer Information :

Manufacturer Name : Kia America, Inc.

Address : 111 Peters Canyon Road Irvine CA 92606 Company phone : 800-333-4542

Population :

Number of potentially involved : 83,667 Estimated percentage with defect : 1 %

🖈 🛝 📩 😡

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

23V-639

Vehicle Information :

Vehicle 1:	2019-2019 Kia Sorento			
Vehicle Type :	LIGHT VEHICLES			
Body Style :	ALL			
Power Train :	GAS			
	Certain 2019 model year Sorento vehicles manufactured from August 1, 2018 through June 12, 2019.			
	The recall population was determined by a review of vehicle production and supplier records. The vehicles subject to this recall were not produced in VIN order. Customers seeking information about their specific vehicle will be referred to Kia's Consumer Assistance Center or their Kia dealer.			
Production Dates :	AUG 01, 2018 - JUN 12, 2019			
VIN Range 1 : Begin : NR End : NR				
Description of Noncomplian				
	 Due to an error in the manufacturing process at the supplier, the rearview camera may be susceptible to water intrusion. If water enters the rear of the camera, the camera's image may become blank while in reverse. As a result, the subject vehicles fail to comply with the rear visibility requirements of Federal Motor Vehicle Safety Standard (FMVSS) 111. 			
FMVSS	I: 111 - Rear visibility			
FMVSS 2	•			
Description of the Safety Risl	c: A rearview camera that does not display what is behind the vehicle increases the risk of crash.			
The inf	formation contained in this report was submitted pursuant to 49 CFR §573			

art 573 Safety Recall Report	23V-639	Pag
Description of the Cause : Supplier's manufacturing error created camera via the wiring harness.	l path for water intrusion into re	arview
dentification of Any Warning None that can Occur :		
volved Components :		
Component Name 1 : CAMERA ASSY-BACK VIEW		
Component Description : Back View Camera Assembly		
Component Part Number : 99240-C6500		
Component Name 2 : CAMERA ASSY-BACK VIEW		
Component Description : Back View Camera Assembly		
Component Part Number: 99240-C6501		
Component Name 3: CAMERA ASSY-BACK VIEW		
Component Description : Back View Camera Assembly		
Component Part Number : 99240-C6600		
applier Identification :		
Component Manufacturer		
Name : Hyundai Mobis Address : 95 Sayang 2-gil, Munbaek-myeon,		
Chungcheongbuk-do Jincheon-gun Foreign States 27862		
Country : Korea, Republic of		
r onology : ee attached document titled "2019MY Sorento Rearview Camera".		

The information contained in this report was submitted pursuant to 49 CFR \$573

Part 573 Safety Re	call Report	23V-639	Page
Description of Remedy :			
Description of Remedy Program :	instructions to bring their vehi- the rearview camera, and if neo issue is found following inspect		l inspect If no water
How Remedy Component Differs from Recalled Component :	v	nts the ability for water to enter the	е
Identify How/When Recall Condition was Corrected in Production :		e rearview camera wiring harness vehicles produced beginning on Ju	
Recall Schedule :			
	2023 and the owner notification November 13, 2023.	uled to begin and end on Novembe n is scheduled to begin and end on	
Planned Owner Notification Date :			

* NR - Not Reported