OMB Control No.: 2127-0004

Part 573 Safety Recall Report

24V-163

Manufacturer Name: Jaguar Land Rover North America, LLC

Submission Date: FEB 29, 2024 NHTSA Recall No.: 24V-163 Manufacturer Recall No.: N871



Manufacturer Information:

Population:

Manufacturer Name: Jaguar Land Rover North America, LLC

Number of potentially involved: 47 Estimated percentage with defect: 100 %

Address: 100 Jaguar Land Rover Way

Mahwah NJ 07495

Company phone: 8188500

Vehicle Information:

Vehicle 1: 2024-2024 LAND ROVER DISCOVERY SPORT

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: NR

Descriptive Information: Jaguar Land Rover is conducting a voluntary safety recall campaign involving 2024

Land Rover Discovery Sport vehicles built at the Halewood Vehicle assembly plant from November 10, 2023 - January 23, 2024. 47 vehicles in the United States and Federalized Territories. The recall population was determined by reviewing build records of vehicles where the righthand-side lower A-pillar bolt may not have been

fastened to the correct torque on some body shells. .

Production Dates: NOV 10, 2023 - JAN 23, 2024

VIN Range 1: Begin: SALCJ2FX8RH342264 End: SALCL2FX9RH345183 ☐ Not sequential

Description of Defect:

Description of the Defect: A concern has been identified where the righthand-side lower A-pillar bolt may

not have been fastened to the correct torque on some body shells. For 7 seat vehicles, it is possible that the body structure may not perform as intended in

certain crash modes.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In the event of a crash, the performance of the body structure may be

impaired, increasing the risk of injury to occupants of the vehicle.

Description of the Cause: NR

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: A-Pillar bolt Component Description: A-Pillar bolt Component Part Number: W711806S443

Supplier Identification:

Component Manufacturer

Name: Jaguar Land Rover Limited

Address: Abbey Road

Whitley, Conventry Foreign States CV3 4LF

Country: United Kingdom

Chronology:

On 06 February 2024, the vehicle assembly plant team discovered through inspection of vehicle build data that a number of vehicles may have been built with the lower A-Pillar bolt on the righthand-side improperly fastened. A stop-shipment was implemented by the vehicle assembly plant and an Update Prior to Sale (UPS) notice issued to affected retailers to suspend the sale of affected vehicles until corrective actions were applied. The Product Safety and Compliance Committee (PSCC) was informed of the issue.

On 13 February 2024, the issue was introduced to the Product Safety and Compliance Committee (PSCC) where confirmation was provided that a number of vehicles had been sold in an unrepaired state.

On 22 February 2024, JLR's Recall Determination Committee (RDC) determined that the issue presented an unreasonable risk to safety and requested that a safety recall be launched to remedy the affected vehicles.

Description of Remedy:

Description of Remedy Program: Vehicles will have the righthand-side lower A-pillar bolt fixing checked and, if necessary, secured. There will be no charge to the owners for this repair. The affected vehicles will be covered under Jaguar Land Rover's new vehicle warranty program. Therefore, reimbursement for pre-notice remedies are not necessary because the affected vehicles are still under warranty.

How Remedy Component Differs NR

from Recalled Component:

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: Notifications to dealers will occur on March 14, 2024. Distribution of

owner notification letters will occur on or before April 19, 2024.

Planned Dealer Notification Date : MAR 14, 2024 - MAR 14, 2024 Planned Owner Notification Date : APR 19, 2024 - APR 19, 2024

* NR - Not Reported