

**Issue Date**

2022-06-24

**Description**

ON YOUR VEHICLE, THE TIRE PRESSURE MONITORING SYSTEM TPMS LIGHT IN YOUR VEHICLES INSTRUMENT CLUSTER MAY NOT ILLUMINATE AS QUICKLY AS INTENDED IF THE TIRE PRESSURE DROPS.

**Safety Risk**

LOW TIRE PRESSURE MAY LEAD TO POOR VEHICLE HANDLING AND A POSSIBLE LOSS OF VEHICLE CONTROL, INCREASING THE RISK OF A CRASH.

**Remedy**

THE BODY CONTROL MODULE BCM IN YOUR VEHICLE NEEDS TO BE UPDATED TO CORRECT THE TIRE PRESSURE MONITORING SYSTEM ALERT POINTS. WE RECOMMEND CHECKING YOUR VEHICLES TIRE PRESSURE AND ENSURE IT MATCHES THE FIGURES PROVIDED ON THE LABEL LOCATED INSIDE THE DRIVER-SIDE FRONT DOOR JAMB. IN ADDITION TO YOUR DEALER BEING ABLE TO UPDATE YOUR VEHICLE NOW, FORD WILL ALSO HAVE THE REMEDY AVAILABLE THROUGH A FORD POWER-UP SOFTWARE UPDATE WITHIN 30 DAYS. FORD WILL NOTIFY YOU WHEN IT IS AVAILABLE.

**Campaign/NHTSA#**

22C15/AWAITING#