

Safety Issue Type: Recalls

November 18 2021 NHTSA Campaign Number: 21V901000

Insufficient Fuel May Cause Stall

Insufficient fuel can cause a stall, increasing the risk of a crash or injury.

NHTSA Campaign Number 21V901000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 357

Summary

Honda (American Honda Motor Co.) is recalling certain 2021 NC750XD motorcycles equipped with 6-speed dual clutch automatic transmissions. The fuel injection control module software may be programmed incorrectly, which can result in insufficient fuel when stopping, or accelerating from a stop.

Remedy

Dealers will reprogram the fuel injection and dual clutch transmission software, free of charge. Owner notification letters are expected to be mailed January 7, 2022. Owners may contact Honda Powersports customer service at 866-784-1870. Honda's number for this recall is KN0.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (1)

Vehicle

MAKE	MODEL	YEAR
HONDA	NC750XD	2021

Associated Documents (3)

Miscellaneous Document - Part 573, Defect Information Report
RMISC-21V901-1789.pdf 60.39KB
<https://static.nhtsa.gov/odi/rcl/2021/RMISC-21V901-1789.pdf>

Defect Notice 573 Report
RCLRPT-21V901-4073.PDF 214.336KB
<https://static.nhtsa.gov/odi/rcl/2021/RCLRPT-21V901-4073.PDF>

Recall Acknowledgement
RCAK-21V901-6961.pdf 645.807KB
<https://static.nhtsa.gov/odi/rcl/2021/RCAK-21V901-6961.pdf>