



Vehicle Health Report

June 2022

Recall Notices



SAFETY RECALL 22TA05 - Certain 2022 Model Year Tundra and Tundra HV - Rear Axle Shafts May Separate from Vehicle During Driving

Vehicles in this recall have certain nuts on the rear axle assembly that can loosen over time and, in some cases, fall off, potentially causing an axle shaft sub-assembly to separate from the axle. If complete separation occurs, this can affect vehicle stability and brake performance, increasing the risk of a crash.

Remedy Available - Jun 23, 2022

Remedy - For all involved vehicles, Toyota dealers will inspect and retighten the axle flange nuts FREE OF CHARGE. In some cases, axle related components may be replaced FREE OF CHARGE based on inspection results.

Service Campaigns

