OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 23V-567

**Manufacturer Name:** General Motors, LLC

Submission Date: AUG 10, 2023 NHTSA Recall No.: 23V-567

**Manufacturer Recall No.:** N232414710



#### **Manufacturer Information:**

Manufacturer Name: General Motors, LLC

Address: 29427 Louis Chevrolet Road

MAIL CODE 480-210-2V WARREN MI

48093

Company phone: 586-596-1733

# **Population:**

Number of potentially involved: 317 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2022-2023 Chevrolet Bolt EV

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : Manufacturing records and part supplier trace records were used to identify vehicles

equipped with an instrument panel from the supplier's suspect production period. Vehicles that were not built with an instrument panel from the supplier's suspect

production period are not part of this recall.

Chevrolet Bolt EUV models use a different panel and are not affected by this recall.

There are 317 Chevrolet Bolt EV vehicles affected by this recall.

Production Dates: APR 16, 2021 - JUN 03, 2023

VIN Range 1 : Begin : NR End : NR ☐ Not sequential

#### **Description of Defect:**

Description of the Defect: General Motors has decided that a defect which relates to motor vehicle safety

may exist in certain 2022-2023 model year Chevrolet Bolt EV vehicles. The instrument panels in these vehicles may have been manufactured without the perforation on the underside of the panel cover that allows the passenger-side

airbag to properly deploy.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: If the perforation is missing, the passenger side airbag may not properly

deploy in a crash, increasing the risk of injury.

Description of the Cause: GM's investigation determined that its Tier 2 supplier allowed unfinished cover

pads to be mixed with finished material and shipped to its Tier 1 supplier for complete instrument panel assembly, and the Tier 1 supplier allowed the unfinished panels to pass through its quality control processes into finished product.

Identification of Any Warning [intentionally left blank] that can Occur:

### **Involved Components:**

Component Name 1: PANEL, INST

**Component Description: Instrument Panel Top Pad** 

Component Part Number: 42801933, 42801935, 42801937

#### **Supplier Identification:**

## **Component Manufacturer**

Name: Yanfeng US Automotive Interior Systems

Address: 1833 Frenchtown Center Drive

Monroe Michigan 48162

**Country: United States** 

#### **Chronology:**

On June 20, 2023, a GM supplier quality engineer was notified by a Tier 1 supplier that some 2022 and 2023 model year Chevrolet Bolt EV vehicles may have been built with instrument panels missing the passenger side airbag perforation. On June 23, 2023, GM opened a product investigation.

GM's investigator retrieved and reviewed field data. The investigator also worked with the Tier 1 and Tier 2 suppliers, and personnel at GM's Orion assembly plant, to define the suspect part population and trace it to vehicles. A total of 403 suspect vehicles were identified. GM is not aware of any field incidents related to this condition.

On August 3, 2023, GM's Safety and Field Action Decision Authority decided to conduct a safety recall.

### **Description of Remedy:**

Description of Remedy Program : Dealers will replace the instrument panel.

Pursuant to 49 C.F.R. § 573.13(d)(1), all covered vehicles are under

warranty, so reimbursement is not offered.

How Remedy Component Differs The replacement instrument panel will be scored properly.

from Recalled Component:

Identify How/When Recall Condition Containment efforts were initiated at GM's assembly plant on June 20, was Corrected in Production: 2023. Vehicles produced on or after June 20, 2023, did not include

instrument panels from the supplier's suspect production period.

# **Recall Schedule:**

Description of Recall Schedule: Dealers will be notified on August 10, 2023. Owner notification is

estimated to begin on September 25, 2023.

Planned Dealer Notification Date: AUG 10, 2023 - AUG 10, 2023 Planned Owner Notification Date: SEP 25, 2023 - SEP 25, 2023

<sup>\*</sup> NR - Not Reported