OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-136

Manufacturer Name: Ferrari North America, Inc.

Submission Date: MAR 01, 2023 NHTSA Recall No.: 23V-136 Manufacturer Recall No.: RC 84



Manufacturer Information:

Manufacturer Name: Ferrari North America, Inc.

Address: 250 Sylvan Avenue

Englewood Cliffs NJ 07632-2500

Company phone: 1800-999-9999

Population:

Number of potentially involved: 13 Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2021-2023 Ferrari SF90

Vehicle Type: LIGHT VEHICLES

Body Style: 2-DOOR

Power Train: HYBRID ELECTRIC

Descriptive Information: Ferrari has determined that a defect related to motor vehicle safety may arise in some

MY 2021 - 2023 Ferrari SF90 vehicles. The issue relates to the use of child seats on M size passenger seats pursuant to FMVSS 208. In particular, in case of an accident, the deployment of an airbag of the passenger M size seat could possibly impact the child seat, thereby potentially causing abnormal body acceleration, which may lead to injuries and/or death. Ferrari has had no reports of any incidents and/or deaths as a consequence of this issue. Affected vehicles: MY 2021 – 2023 Ferrari SF90 Coupe; MY

2022 Ferrari SF90 Spider.

Production Dates: JAN 11, 2021 - NOV 03, 2022

VIN Range 1: Begin: ZFF95NLA6M0263594 End: ZFF95NLAXP0287661 ✓ Not sequential

Description of Defect:

Description of the Defect: Ferrari has determined that a defect related to motor vehicle safety may arise

in some MY 2021 - 2023 Ferrari SF90 vehicles. The issue relates to the use of child seats on M size passenger seats pursuant to FMVSS 208. In particular, in case of an accident, the deployment of an airbag of the passenger M size seat could possibly impact the child seat, thereby potentially causing abnormal

body acceleration, which may lead to injuries and/or death.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Upon deployment of the passenger airbag, such deployment can impact the

child seat, thereby potentially causing abnormal body acceleration, which

may lead to injuries and/or death to the vehicle passenger.

Description of the Cause: Passenger seats size M installed on SF90 model (where equipped with child

seats) do not comply with FMVSS 208.

Identification of Any Warning Not applicable.

that can Occur:

Involved Components:

Component Name 1: passenger seat (M size)

Component Description: passenger seat (M size)

Component Part Number: 000917105 Basic version (M size)

Component Name 2: passenger seat (M size)

Component Description: passenger seat (M size)

Component Part Number: 000917113 Daytona version (M size)

Supplier Identification:

Component Manufacturer

Name: Sabelt S.p.A.

Address: Via Guido Rossa, 10

Moncalieri (TO) Foreign States 10024

Country: Italy

Chronology:

See attached chronology.

Description of Remedy:

Description of Remedy Program: The repair consists of replacing the M size passenger seat with an XL size

passenger seat. Ferrari will send a notice letter to all affected vehicle owners to warn them of this issue, and instruct them 1) to contact an authorized Ferrari dealer to schedule the free recall repair, and 2) that in the meantime, request them not to use/install any child seats on board of

the vehicles.

How Remedy Component Differs The size of the passenger seats that will be upgraded to XL size.

from Recalled Component:

Identify How/When Recall Condition All SF90 vehicles currently in production have been fitted with XL size

was Corrected in Production: passenger seats starting from February 21, 2023.

Recall Schedule:

Description of Recall Schedule: The client notification letter will be sent to all known current owners of

the affected vehicles advising them to contact an authorized Ferrari dealer to schedule an appointment to have the recall work performed.

The letters are scheduled to be sent on or before April 30, 2023.

Planned Dealer Notification Date : APR 30, 2023 - NR Planned Owner Notification Date : APR 30, 2023 - NR

^{*} NR - Not Reported