

Home / Recalls / REC-005842

Isuzu Ute Australia Pty Ltd - ISUZU D-MAX 2021 - 2023

Recall number

REC-005842

Campaign number

S202308

Original published date

28 November 2023

Make

ISUZU

Model

D-MAX

Year range

2021 - 2023

Affected units

8,039

Variant applicability

All variants within this model

Identifying features

国 REC-005842-VIN-List-1.csv (CSV, 149.19 KB)

What are the defects?

Due to a manufacturing issue, the fuel hose may chafe against the engine oil level bracket and become damaged. If this occurs, fuel may leak in the presence of an external ignition source resulting in a vehicle fire.

What are the hazards?

A vehicle fire could increase the risk of injury or death to vehicle occupants, other road users or bystanders and/or damage to property.

What should consumers do?

Owners of affected vehicles can contact their nearest authorised Isuzu UTE dealer service department, to schedule an appointment to have the fuel hose and retaining clips replaced free of charge.

Supplier details

Isuzu Ute Australia Pty Ltd

Who should owners/operators contact for more information?

Contact name

Isuzu UTE Australia Customer Relations Department

Contact phone

1300 147 898

Contact email

info@iua.net.au

Contact website

https://www.isuzuute.com.au

Responsible regulator

Department of Infrastructure, Transport, Regional Development, Communications and the Arts is the responsible regulator for this recall.



Product type

Cars

ISUZU

Share this page 😝 🂆 🛅 💌

I want to...



Receive email updates



Subscribe to RSS



Browse all recalls

Recalls Browse all recalls Cars Motorbikes Caravans and Motorhomes Trucks and Buses Trailers **Guidance for suppliers** News Receive email updates 🗹 About us Resources Contact us The Department of Infrastructure, Transport, Regional Development, Communications and the Arts acknowledges the Traditional Custodians of Country throughout Australia. **(1)** in Copyright 🗹 Disclaimer 🗹 Privacy 🗹 ABN: 86 267 354 017