# Part 573 Safety Recall Report

Manufacturer Name :Chrysler (FCA US, LLC)Submission Date :NOV 23, 2022NHTSA Recall No. :22V-865Manufacturer Recall No. :ZB7

## Manufacturer Information :

Manufacturer Name : Chrysler (FCA US, LLC) Address : 800 Chrysler Drive CIMS 482-00-91 Auburn Hills MI 48326-2757 Company phone : 1-800-853-1403

## Vehicle Information :

	021-2023 Jeep Wrangler		
Vehicle Type :			
Body Style : St			
Power Train : N	2		
	me 2021-2023 MY Jeep Wrangler 4xe vehicles equipped with the 2.0L Plug-in /brid Electric Vehicle ("PHEV") engine.		
be uj ar Si	The suspect period began on September 2, 2020, when the 2021 MY production began, and ended on August 17, 2022, when the 2023 MY production began with updated vehicle control software. The suspect period was determined using supplier and vehicle production records. Similar vehicles not included in the recall population are not equipped with the PHEV engine or were built after the suspect period.		
Production Dates · SI	EP 02, 2020 - AUG 17, 2022		
roduction butes. Si			
VIN Range 1 : Beg			
VIN Range 1 : Beg Description of Defect :			
VIN Range 1 : Beg Description of Defect :	gin: NR End: NR Dot sequential		
VIN Range 1 : Beg Description of Defect : Description of the Defect :	gin: NR End: NR Dot sequential Not sequential Some 2021-2023 MY Jeep Wrangler 4xe vehicles equipped with the 2.0L PHEV may experience an engine shut down condition caused by diagnostic reactions to faults caused by loss of communication.		
VIN Range 1 : Beg Description of Defect : Description of the Defect : FMVSS 1 : FMVSS 2 :	gin: NR End: NR Ind: NR Not sequential Some 2021-2023 MY Jeep Wrangler 4xe vehicles equipped with the 2.0L PHEV may experience an engine shut down condition caused by diagnostic reactions to faults caused by loss of communication. NR NR An engine shut down condition may result in an unexpected loss of motive power while driving, which can cause a vehicle crash without prior warning.		

ATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

22V-865

## **Population :**

Number of potentially involved : 62,909 Estimated percentage with defect : 100 %

The information contained in this report was submitted pursuant to 49 CFR \$573

## Part 573 Safety Recall Report

Identification of Any Warning None that can Occur :

#### **Involved Components :**

Component Name 1 :Unknown. Root cause is under investigation.Component Description :Unknown. Root cause is under investigation.Component Part Number :Unknown. Root cause is under investigation.

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Not a different manufacturer

Address : NR

NR

Country: NR

#### Chronology :

• On September 8, 2021, FCA US LLC ("FCA US") Technical Safety and Regulatory Compliance ("TSRC") opened an investigation into 2021-2023 MY Wrangler 4xe PHEVs for a loss of motive power.

• From September 2021, through October 2022, FCA US TSRC conducted an analysis of stall reports and vehicle history and determined that the affected vehicles reported multiple cause and correction details with varied commonality.

• As of November 3, 2022, FCA US is aware of 112 customer assistance records, 196 warranty claims, and 65 field reports potentially related to this issue for all markets with dates of receipt ranging from December 17, 2020, to October 26, 2022.

• As of November 3, 2022, FCA US is aware of two accidents and one injury potentially related to this issue for all markets.

• On November 17, 2022, FCA US determined, through the Vehicle Regulations Committee, to conduct a voluntary safety recall of the affected vehicles.

The information contained in this report was submitted pursuant to 49 CFR §573

## **Description of Remedy :**

Description of Remedy Program :	FCA US will conduct a voluntary safety recall on all affected vehicles to update vehicle control software.
	FCA US has a longstanding policy and practice of reimbursing owners who have incurred the cost of repairing a problem that subsequently becomes the subject of a field action. To ensure consistency, FCA US, as part of the owner letter, will request that customers send the original receipt and/or other adequate proof of payment to the company for confirmation of the expense.
	Remedy is updated calibration software in the Transmission Control Module, Hybrid Control Processor and Auxiliary Hybrid Control Processor
Identify How/When Recall Condition was Corrected in Production :	NR

## **Recall Schedule :**

Description of Recall Schedule :	**11/23/2022: FCA US will notify dealers and begin notifying owners on
	or about 01/12/2023.
Planned Dealer Notification Date :	JAN 12, 2023 - JAN 12, 2023
Planned Owner Notification Date :	JAN 12, 2023 <sup>-</sup> JAN 12, 2023

\* NR - Not Reported