



Motor Vehicle Safety Recalls Database

- [New Search](#)
- [Advanced Search](#)
- [Modify Search](#)
- [Main Menu](#) ▼

[Motor Vehicle Safety](#) > [Vehicle Recalls and Defects](#) > [Motor Vehicle Safety Recalls Database](#)

Recall Details

Transport Canada Recall # 2024-093

Recall Date	2024-02-14
Last Updated	2024-02-22
Notification Type	Safety Mfr
System	Electrical
Issued by	KIA
Manufacturer Recall Number	RC199
Units Affected <small> ⓘ</small>	44,478
Category	SUV

Recall Details

Issue:

On certain vehicles, the 4WD control unit under the driver's seat may become contaminated by a mixture of salt and moisture inside the vehicle. Over time, this can lead to corrosion that could cause a short circuit.

Note: This recall only affects vehicles equipped with all-wheel drive.

Safety Risk:

A short circuit can create a fire risk, even while the vehicle is parked and turned off.

Corrective actions:

Kia will notify owners by mail and advise you to take your vehicle to a dealership to inspect the 4WD control unit. The control unit and other components will be replaced as necessary. The dealer will also install a protective cover over the 4WD control unit. Kia advises that you should park your vehicle outdoors and away from other vehicles or structures until the recall repairs have been completed.

Make	Model	Model Year(s) Affected
------	-------	------------------------

KIA	SELTOS	2021 2022 2023
-----	--------	----------------

Manufacturer Name	Contact Number	Web Site
KIA	1-877-542-2886	CHECK IF THIS RECALL APPLIES TO YOUR VEHICLE

[Report a problem on this page](#)

[Share this page](#)