



Australian Government

Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts



[Home](#) / [Recalls](#) / REC-005855

# Lotus Cars Limited. - LOTUS 131 / Emira 2022

**Recall number**

REC-005855

**Campaign number**

2023/01R

**Original published date**

19 December 2023

**Make**

LOTUS

**Model**

131 / Emira

**Year range**

2022

**Affected units**

26

**Variant applicability**

All variants within this model

## Identifying features

## VIN (Vehicle identification number)



REC-005855-VIN-List-1.csv (CSV, 524 bytes)

## What are the defects?

Due to a defect during assembly, the driver and passenger's seatbelt locking mechanism may engage at the incorrect point. As a result, the seatbelt could engage tightly across the chest and waist and limit movements which may lead to restricted visibility. Additionally, the seatbelt could require increased effort to unbuckle.

## What are the hazards?

Limited movement and restricted visibility for the driver may increase the risk of an accident causing serious injury or death to vehicle occupants and other road users. In the event of an emergency exit from the vehicle an increased effort to unbuckle the seatbelt could increase the risk of serious injury or death to vehicle occupants.

## What should consumers do?

Owners of affected vehicles will be contacted directly by their Lotus dealer to arrange a service date for replacement of the seatbelts, free of charge.

For further information, contact Lotus Cars Australia Customer Care by email [customercare@lotuscars.com.au](mailto:customercare@lotuscars.com.au).

---

### Supplier details

Lotus Cars Limited.

## Who should owners/operators contact for more information?

### Contact name

Lotus Cars Limited

### Contact email

customercare@lotuscars.com.au

**Contact website**

<http://www.lotuscars.com> 

## Responsible regulator

Department of Infrastructure, Transport, Regional Development, Communications and the Arts is the responsible regulator for this recall.



**Australian Government**

**Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts**

## Product type

Cars

LOTUS

Share this page    

### I want to...



Receive email updates



Subscribe to RSS



[Browse all recalls](#)

### Recalls

[Browse all recalls](#)

[Cars](#)

[Motorbikes](#)

[Caravans and Motorhomes](#)

[Trucks and Buses](#)

[Trailers](#)

### Guidance for suppliers

### News

[Receive email updates](#)

### About us

[Resources](#)

### Contact us

The Department of Infrastructure, Transport, Regional Development, Communications and the Arts acknowledges the Traditional Custodians of Country throughout Australia.



[Copyright](#)

[Disclaimer](#)

[Privacy](#)

ABN: 86 267 354 017



Australian Government

Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts



[Home](#) / [Recalls](#) / REC-005857

# Lotus Cars Limited. - LOTUS 131 / Emira 2022 - 2023

**Recall number**

REC-005857

**Campaign number**

2023/03R

**Original published date**

19 December 2023

**Make**

LOTUS

**Model**

131 / Emira

**Year range**

2022 - 2023

**Affected units**

101

**Variant applicability**

All variants within this model

## Identifying features

## VIN (Vehicle identification number)

 REC-005857-VIN-List-1.csv (CSV, 1.9 KB)

## What are the defects?

Due to a manufacturing defect, the driver and passenger side A-pillar trims may have been fitted incorrectly. As a result, in an event of the side curtain airbags deployment the force from the airbag could cause the A-pillars cover to detach.

## What are the hazards?

If the A-pillar trim detaches, plastic fragments may be propelled towards the vehicle occupants causing serious injury or death.

## What should consumers do?

Owners of affected vehicles will be contacted directly by their Lotus dealer to arrange for replacement of the vehicle A-pillar trim assembly, free of charge.

For further information, contact Lotus Cars Australia Customer Care by email at [customercare@lotuscars.com.au](mailto:customercare@lotuscars.com.au).

---

### Supplier details

Lotus Cars Limited.

## Who should owners/operators contact for more information?

### Contact name

Lotus Cars Limited

### Contact email

[customercare@lotuscars.com.au](mailto:customercare@lotuscars.com.au)

### Contact website

<https://www.lotuscars.com> 

# Responsible regulator

Department of Infrastructure, Transport, Regional Development, Communications and the Arts is the responsible regulator for this recall.



**Australian Government**

**Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts**

## Product type

Cars

LOTUS

Share this page    

## I want to...



Receive email updates



Subscribe to RSS



Browse all recalls

## Recalls

[Browse all recalls](#)

[Cars](#)

[Motorbikes](#)

[Caravans and Motorhomes](#)

[Trucks and Buses](#)

[Trailers](#)

## Guidance for suppliers

## News

[Receive email updates](#) 

## About us

[Resources](#)

## Contact us

The Department of Infrastructure, Transport, Regional Development, Communications and the Arts acknowledges the Traditional Custodians of Country throughout Australia.



[Copyright](#) 

[Disclaimer](#) 

[Privacy](#) 

ABN: 86 267 354 017





Australian Government

Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts



[Home](#) / [Recalls](#) / REC-005856

# Lotus Cars Limited. - LOTUS 131 / Emira 2022 - 2023

**Recall number**

REC-005856

**Campaign number**

2023/02R

**Original published date**

19 December 2023

**Make**

LOTUS

**Model**

131 / Emira

**Year range**

2022 - 2023

**Affected units**

76

**Variant applicability**

All variants within this model

## Identifying features

## VIN (Vehicle identification number)

 REC-005856-VIN-List-1.csv (CSV, 1.44 KB)

## What are the defects?

Due to a software issue, the windscreen wipers may operate at half the required speed. In the event of heavy rain this may lead to poor visibility for the driver.

## What are the hazards?

Poor visibility will potentially increase the risk of an accident, causing serious injury or death to vehicle occupants and other road users.

## What should consumers do?

Owners of affected vehicles will be contacted directly by their Lotus dealer to arrange for replacement of the windscreen wipers motor assembly, free of charge.

For further information, contact Lotus Cars Australia Customer Care by email at [customercare@lotuscars.com.au](mailto:customercare@lotuscars.com.au).

---

### Supplier details

Lotus Cars Limited.

## Who should owners/operators contact for more information?


### Contact name

Lotus Cars Limited

### Contact email

[customercare@lotuscars.com.au](mailto:customercare@lotuscars.com.au)

### Contact website

<https://www.lotuscars.com> 

# Responsible regulator

Department of Infrastructure, Transport, Regional Development, Communications and the Arts is the responsible regulator for this recall.



**Australian Government**

**Department of Infrastructure, Transport,  
Regional Development, Communications and the Arts**

## Product type

Cars

LOTUS

Share this page



## I want to...



Receive email updates



Subscribe to RSS



Browse all recalls

## Recalls

[Browse all recalls](#)

[Cars](#)

[Motorbikes](#)

[Caravans and Motorhomes](#)

[Trucks and Buses](#)

[Trailers](#)

## Guidance for suppliers

### News

[Receive email updates](#) 

## About us

[Resources](#)

## Contact us

The Department of Infrastructure, Transport, Regional Development, Communications and the Arts acknowledges the Traditional Custodians of Country throughout Australia.



[Copyright](#) 

[Disclaimer](#) 

[Privacy](#) 

ABN: 86 267 354 017