

GM 2014 YEAR-TO-DATE NORTH AMERICAN RECALLS INCLUDING EXPORTS

#	DATE	MY/MODELS	SUBJECT	U.S. POPULATION	GMNA POPULATION
1	1/13	2014 Chevrolet Silverado and GMC Sierra full-size pickups	Overheated Exhaust Components	324,970	377,888
2	1/23	2014 Chevrolet Trax/Tracker (Mexico and export only)	Fuel Line Quick Connector	0	2,069
3	2/20	2014 Buick Enclave, LaCrosse, Regal, and Verano; 2014 Chevrolet Cruze, Impala, Malibu and Traverse, GMC Acadia	Transmission Shift Cable Adjuster Body Fractures	355	388
4	2/25	2005-07 Chevrolet Cobalt, Pontiac G5 and Pursuit 2003-07 Saturn ION; 2006-07 Chevrolet HHR; 2006-07 Pontiac Solstice; 2007 Saturn Sky, Opel/Vauxhall GT, Daewoo G2X	Ignition Switch Torque Performance	1,367,146	1,620,665
5	3/17	2013-14 Cadillac XTS	Brake Vacuum Booster Pump Vent and Connector	63,903	66,218
6	3/17	2009-14 Chevrolet Express and GMC Savana	Front Passenger Airbag Performance	303,013	354,553
7	3/17	2008-13 Buick Enclave, Chevrolet Traverse, GMC Acadia, Saturn Outlook	Side Impact Airbag Connector	1,176,407	1,334,986
8	3/28	2014 Cadillac ELR	Electronic Brake Control Module Calibration	656	662
9	3/28	2008-11 Chevrolet HHR; 2008-10 Chevrolet Cobalt; 2008-10 Pontiac G5; 2008-10 Pontiac Solstice; 2008-10 Saturn Sky; 2008-10 Opel GT; 2008-09 Daewoo G2X	Ignition Switch Torque Performance	823,788	970,741
10	3/28	2013 and 2014 MY Chevrolet Cruze models equipped with 1.4L turbocharged engine (RPO LUV)	Half Shaft Fracture	174,046	197,327
11	3/28	2014-15 full-size trucks and full-size utilities with MYC transmission	Oil Cooler Fitting	489,936	559,249
12	3/31	2004-06 Chevrolet Malibu/Malibu Maxx, Pontiac G6; 2004-07 Saturn ION; 2008-09 Chevrolet Malibu, Pontiac G6, Saturn Aura; 2010 Cobalt; 2009-10 Chevrolet HHR; Previous EPS Recall Service Parts	Electronic Power Steering	1,340,447	1,508,445
13	4/9	2005-2010 Chevrolet Cobalt; 2006-2011 Chevrolet HHR; 2003-2010 Pontiac G5; 2006-2010 Pontiac Solstice; 2003-2007 Saturn ION; 2007-2010 Saturn Sky	Ignition Cylinder	2,191,014	2,591,406
14	4/19	2009-2010 Pontiac Vibe	Air Bags (Toyota)	23,249	40,514
15	4/24	2013 Cadillac SRX	Hesitation	50,571	56,367
16	4/24	2015 Chevrolet Silverado HD and GMC Sierra HD	Diesel Transfer Pump	51	59
17	4/29	2014 Chevrolet Traverse, GMC Acadia and Buick Enclave	Inaccurate Fuel Gauge	51,640	57,131
18*	4/29	2007-2008 Saturn Aura	Shift Cable	56,214	59,627
	5/19	2004-2008 Chevrolet Malibu; 2005-2008 Pontiac G6	Shift Cable	1,074,932	1,215,791
19	5/7	2014 Chevrolet Malibu and Buick LaCrosse	Brake Rotors	8,208	8,590
20	5/13	2014 Chevrolet Malibu	Brake Boost	140,067	144,780
21	5/13	2014 Chevrolet Silverado and GMC Sierra Light Duty; 2015 Chevrolet Tahoe	Tie-rods	477	523
22	5/14	2005-2007 Chevrolet Corvette	Low Beams	103,158	111,889
23	5/14	2014 Cadillac CTS	Wipers	19,225	21,563
24	5/14	2004-2012 Chevrolet Malibu; 2004-2007 Malibu Maxx; 2005-2010 Pontiac G6; 2007-2010 Saturn Aura	Brake Lamps	2,440,524	2,703,657
25	5/16	2015 Cadillac Escalade	Passenger Air Bag	1,402	1,533
26	5/19	2009-2010 Saturn Outlook; 2009-2014 Chevrolet Traverse, GMC Acadia and Buick Enclave	Front Seat Belts	1,339,355	1,509,523
27	5/19	2015 Chevrolet Silverado HD and GMC Sierra HD	Loose Fuse Block	58	58
28	5/21	2004-2008 Chevrolet Aveo; 2005-2008 Pontiac Wave, G3	Daytime Running Lamps	217,454	284,699
29	5/21	2004-2008 Chevrolet Optra (Imported from GM Korea; sold in U.S. Territories)	Daytime Running Lamps	214	214
30	5/30	Certain 2014 Chevrolet Silverado and GMC Sierra; 2015 Chevrolet Tahoe and Suburban, GMC Yukon and Yukon XL and Cadillac Escalade and Escalade ESV	Sensing and Diagnostic Module	334	344
31	6/5	Certain 2014 Chevrolet Silverado LD; 2014 GMC Sierra LD; 2015 Silverado HD, Tahoe and Suburban; 2015 GMC Sierra HD, Yukon and Yukon XL	Base Radio Chime	57,512	69,552
32	6/5	Certain 2013 and 2014 Chevrolet Spark and 2013 Buick Encore	Passenger Air Bag	61	87
33	6/5	Certain 2012 Chevrolet Cruze, Camaro, Sonic and Buick Verano	Driver's Air Bag Shorting Bar	31,520	36,012
34	6/5	2014 Chevrolet Corvette	Sensing and Diagnostic Module	33	37
35	6/11	2004-2011 Saab 9-3 Convertible	Seat Belt Retractor	28,789	29,750
36	6/11	2012 Chevrolet Sonic	Transmission Turbine Shaft Fracture	21,567	24,904
37	6/11	2014 Buick LaCrosse	Driver's Door Wiring Splice	14,765	15,185
38	6/13	2010-2014 Chevrolet Camaro	Key FOB Can Bump Ignition	464,712	511,528
39	6/16	2005-2009 Buick Allure and Buick LaCrosse; 2006-2014 Chevrolet Impala; 2000-2005 Cadillac Deville; 2004-2011 Cadillac DTS; 2006-2011 Buick Lucerne; 2004-2005 Buick Regal LS & GS; 2006-2008 Chevrolet Monte Carlo	Key Replacement from Slot to Hole	3,160,725	3,360,555
40	6/16	2013-2014 Cadillac ATS and 2014 Cadillac CTS	Shift Cable	90,750	109,031
41	6/16	2015 Chevrolet Silverado 2500/3500 HD and GMC Sierra 2500/3500 HD	Steering Pump Clamp Inspection	57,192	65,125
42	6/16	2011 Cadillac AWD CTS	Roof Rail Air Bags	16,932	18,279
43	6/16	2014 Chevrolet Corvette with Competition Sport Seats	Incorrect Air Bag	712	961
44	6/16	2014-2015 Chevrolet Silverado and GMC Sierra	Unsecured Floor Mats	184	184

*Shift Cable is a single recall initiated 4/29 and expanded 5/19

U.S. TOTAL
17,728,268

GMNA TOTAL
20,033,649