30

OMB Control No.: 2127-0004

## **Part 573 Safety Recall Report**

## Manufacturer Name : Newmar Corporation Submission Date : DEC 02, 2022 NHTSA Recall No.: 22V-890 Manufacturer Recall No.: NR

### **Manufacturer Information :**

Manufacturer Name : Newmar Corporation

Address: 355 North Delaware Street PO Box 30 Nappanee IN 46550 Company phone : 574-773-7791

### **Vehicle Information :**

Descriptive Information :	On certain Newmar Supreme Aire Class C motorhomes, the cap screws under the steering wheel cover could work loose. The loose screws could cause the steering wheel to come loose from the steering wheel adaptor, which could then separate from the steering column. The loose steering wheel could cause the inability to steer the unit which could increase the risk of a crash. 2022 SACC = 26 2023 SACC = 4
Production Dates :	MAR 03, 2021 - SEP 07, 2022
VIN Range 1:	Begin :NREnd :NRNot sequential

### **Description of Defect :**

Description of the Defect :	On certain Newmar Supreme Aire Class C motorhomes, the cap screws under the steering wheel cover could work loose. The loose screws could cause the steering wheel to come loose from the steering wheel adaptor, which could then separate from the steering column. The loose steering wheel could cause the inability to steer the unit which could increase the risk of a crash.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Loose steering wheel could cause the inability to steer the unit which could increase the risk of a crash.
Description of the Cause :	The cap screws under the steering wheel cover could work loose. The loose screws could cause the steering wheel to come loose from the steering wheel adaptor, which could then separate from the steering column.



Number of potentially involved :

Estimated percentage with defect : 100 %

**Population :** 

## 22V-890

## Part 573 Safety Recall Report

22V-890

Identification of Any Warning Feel the steering wheel becoming loose during use. that can Occur :

#### **Involved Components :**

Component Name 1 : Steering Wheel Component Description : Steering Wheel Component Part Number : NR

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : Steering Creations, Inc

- Address: 519 SW 31st Ave
  - Ocala Florida 34474
- **Country : United States**

#### **Chronology** :

8/16/22 – Newmar received notice that a customer had an issue with the steering wheel coming loose. This was investigated and it was found that the cap screws under the steering wheel had worked loose. The steering wheel was fixed at the Newmar Service Center when it was determined what the cause of the loose steering wheel was.

10/31/22 – Newmar production noticed several steering wheels felt loose, 6 units in production were found with loose steering wheels and were fixed prior to leaving production with instructions from the steering wheel supplier, Steering Creations, Inc.

11/28/22 – The loose steering wheel issue was brought to the Safety Committee for review and it was decided to issue a recall for all units that have used the steering wheel supplied by Steering Creations, Inc.

#### **Description of Remedy :**

<b>Description of Remedy Program :</b>	All units will have the cap screws removed and then re-install the steering
	wheel cap screws with Loctite applied and the screws re-torqued down to
	3.5 Ft/Lbs. as directed by the steering wheel supplier, Steering Creations,
	Inc. All repairs will be at no cost to customer.

The information contained in this report was submitted pursuant to 49 CFR §573

# Part 573 Safety Recall Report

22V-890

Page 3

How Remedy Component Differs from Recalled Component :	
	The cap screws removed and then re-install the steering wheel cap screws with Loctite applied and the screws re-torqued down to 3.5 Ft/Lbs. as
	directed by the steering wheel supplier, Steering Creations, Inc.
Recall Schedule :	directed by the steering wheel supplier, steering creations, inc.
	Customer and Dealer notification will be sent out on or before 60 days
<b>Recall Schedule :</b> Description of Recall Schedule : Planned Dealer Notification Date :	Customer and Dealer notification will be sent out on or before 60 days from the date of this filing, 1/31/2023.

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573