

U.S. Department of Transportation

National Highway Traffic Safety Administration

ODI RESUME

Investigation: DP 23-003

Prompted by: **DEFECT PETITION**

Date Opened: 07/25/2023

Investigator: Alexa Overstreet Reviewer: Gregory Magno

Approver: Tanya Topka

Subject: Malfunction Indicator Light / No-Start

MANUFACTURER & PRODUCT INFORMATION

Manufacturer: Mercedes-Benz USA, LLC **Products:** 2023 Mercedes-Benz GLC300

8,000 (Estimated) Population:

Problem Description: The petition alleges that subject vehicle contains a defect that can cause the frequent

illumination of the engine warning light and the inability to start the vehicle.

FAILURE REPORT SUMMARY

	ODI	Manufacturer	Total
Complaints:	0	0	0
Crashes/Fires:	0	0	0
Injury Incidents:	0	0	0
Fatality Incidents:	0	0	0
Other*:	1	0	0

*Description of Other: Defect Petition

ACTION / SUMMARY INFORMATION

Action: Further evaluation of Defect Petition for a grant or deny decision.

Summary:

The Office of Defects Investigation (ODI) of the National Highway Traffic Safety Administration received a petition dated July 2, 2023, requesting an investigation of an alleged defect involving the 48V mild hybrid system in Model Year 2023 Mercedes-Benz GLC300 vehicles.

The petitioner alleges that a defect in the 48V mild hybrid system is resulting in the frequent illumination of the engine warning light and the inability to start the vehicle. This defect petition has been opened to evaluate the allegation and determine whether to grant or deny the petitioner's request.

The petition can be reviewed at NHTSA.gov under reference ODI number 11533472.

Investigation: DP 23-003 Open Resume Page 1 of 1