Part 573 Safety Recall Report

Manufacturer Name :Nissan North America, Inc.Submission Date :SEP 01, 2022NHTSA Recall No. :22V-666Manufacturer Recall No. :PC915

Manufacturer Information :

Manufacturer Name : Nissan North America, Inc. Address : P. O. BOX 685001 Franklin TN 37068-5009 Company phone : 800-647-7261

Vehicle Information :

Vehicle 1:	2021-2022 Nissan Rogue
	LIGHT VEHICLES
Body Style :	SUV
Power Train :	GAS
Descriptive Information :	This issue is specific to Nissan Rogue vehicles produced during the specified production period. No other Nissan or INFINITI vehicles are affected.
Production Dates :	MAR 23, 2022 - APR 14, 2022
VIN Range 1:	Begin :NREnd :NRNot sequential

Population :

Description of Noncompliance :

	During a routine audit, Nissan identified the rear seat belts for the left-hand and right-hand rear seats were not retracting properly. In this condition, the seat belt assembly would not comply with S7.1 of FMVSS 208; Occupant crash protection and S4.3 of FMVSS 209; Seat Belt standards.
FMVSS 1 :	208 - Occupant crash protection
FMVSS 2 :	209 - Seat belt assemblies
Description of the Safety Risk :	If the seat belts do not retract properly, there may be difficulty in pulling the seat belt out of the retractor thus preventing its usage; which may lead to injury in an accident.
Description of the Cause :	NR
Identification of Any Warning that can Occur :	There will be visual slack in the seat belts and/or the seat belts will retract slowly.

Involved Components :

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 8,391 Estimated percentage with defect : 1 %

22V-666

Part 573 Safety Recall Report

22V-666

Component Name 1:	BELT ASSY – TOUNGE, PRETENS RR			
Component Description :				
Component Part Number :				
Component Name 2 :	BELT ASSY – TOUNGE, PRETENS RR			
Component Description :	REAR LH - BLACK			
Component Part Number :	88884 6RR3A			
•	BELT ASSY – TOUNGE, PRETENS RR			
Component Description :				
Component Part Number :	88885 6RR3B			
•	BELT ASSY – TOUNGE, PRETENS RR			
Component Description :				
Component Part Number :	88884 6RR3B			
Component Name 5 :	BELT ASSY – PRETENS			
-	SERVICE PART - PRETENS			
Component Part Number :				
	oooo omija			
Supplier Identification :				
Component Manufacturer				
Name : ZF TRW Safety Systems Inc.				
Address : Circuito del Ferrocarril 160				
Gomez Palacio Durango Foreign States 35024				
Country : Mexico				

Chronology :

On April 14, 2022, during a routine quality audit, a Nissan technician found the rear seat belts not retracting

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Page 3

properly on a MY2022 Rouge vehicle and alerted the Supplier of the concern. Together with Nissan, the supplier launched an investigation.

May 2022 – During the Tier 1 supplier's (ZF) investigation, a tooling issue was discovered within the seat belt assembly process that caused non-uniform bending of the internal retractor base bracket. As a result, the internal spool can bind, leading to difficulty or inability to extract or retract the seat belt properly.

June 2022 through August 2022 – Nissan conducted a safety assessment to evaluate the regulatory impact of the subject condition. During this time, Nissan worked with the supplier to conduct testing on multiple seat belt fixtures to duplicate the concern.

Nissan completed its safety assessment and concluded that although the seat belt assemblies would perform as intended in an accident and restrain the occupant, the subject seat belt assemblies did not meet certain regulatory requirements for seat belt fitting, ALR retention, and retraction force.

August 25, 2022 – Nissan decided to conduct a Voluntary Recall to inspect all potentially affected vehicles and repair if necessary.

Nissan is not aware of any warranty claims attributed to the subject condition.

Description of Remedy :

	Description of Remedy Program :	Dealers will inspect both left-hand and right-hand rear seat belts and replace as necessary. All inspections and repairs will be performed free of shours for parts and labor
		charge for parts and labor. Nissan will not include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification
		remedy for the subject vehicles because they are still under warranty.
	How Remedy Component Differs from Recalled Component :	
de	ntify How/When Recall Condition was Corrected in Production :	

Recall Schedule :

Description of Recall Schedule :	Nissan will notify all owners of affected vehicles by October 27, 2022.
	Dealers will be notified on September 7, 2022.
Planned Dealer Notification Date :	SEP 07, 2022 - NR
Planned Owner Notification Date :	OCT 27, 2022 - NR

* NR - Not Reported