

## **Safety Issue Type: Recalls**

**August 30 2022** NHTSA Campaign Number: 22V656000

### **Headlight Adjustment Screw Missing Cover/FMVSS 108**

Improperly adjusted headlights may not illuminate the road properly, or cause a glare to oncoming drivers, which can increase the risk of a crash.

**NHTSA Campaign Number** 22V656000

**Manufacturer** Porsche Cars North America, Inc.

#### **Components**

**Potential Number of Units Affected** 193259

#### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2003-2020 Porsche Macan, Cayenne, Panamera, and Cayman S vehicles. Please see the recall report for a complete list of all affected models and model years. The caps that cover the low-beam headlight horizontal adjustment screws are missing, which can allow the headlights to be improperly adjusted. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

#### **Remedy**

Dealers will inspect the headlights for sealing caps and install missing caps as necessary, free of charge. Owner notification letters are expected to be mailed October 29, 2022. Owners may contact Porsche's customer service at 1-800-767-7243. Porsche's number for this recall is ANB4.

#### **Notes**

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to [www.nhtsa.gov](http://www.nhtsa.gov).