OMB Control No.: 2127-0004

Part 573 Safety Recall Report

23V-842

Manufacturer Name: Volkswagen Group of America, Inc.

Submission Date: DEC 19, 2023 **NHTSA Recall No.:** 23V-842 **Manufacturer Recall No.:** 93U6/93U8



Manufacturer Information:

Manufacturer Name: Volkswagen Group of America, Inc.

Address: 3800 Hamlin Road

Auburn Hills MI 48326

Company phone: 1-800-893-5298

Population:

Number of potentially involved: 93,196 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2022-2024 AUDI RS E-TRON GT

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

RS E-TRON GT: 1579

93U6

Production Dates: MAR 18, 2021 - OCT 11, 2023

VIN Range 1: Begin: WAUAHBFW4N7900626 End: WAUBHBFW2R7900800 ✓ Not sequential

Vehicle 2: 2020-2021 AUDI A8

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

A8: 165 93U6

Production Dates: DEC 02, 2019 - NOV 29, 2021

VIN Range 1:Begin: WAU8HAF89LN008164 End: WAU8HAF81MN032086 ✓ Not sequential

Vehicle 3: 2022-2024 AUDI E-TRON GT

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON GT: 4991

93U6

Production Dates: MAR 26, 2021 - OCT 17, 2023

VIN Range 1: Begin: WAUEJBFW4R7000921 End: WAUEJBFW2R7001694 ✓ Not sequential

Vehicle 4: 2019-2024 AUDI E-TRON QUATTRO

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON QUATTRO: 33288

93U6

Production Dates: JAN 03, 2019 - NOV 09, 2023

Vehicle 5: 2020-2024 AUDI E-TRON SPORTBACK QUATTRO

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON SPORTBACK QUATTRO: 9020

93U6

Production Dates: MAY 20, 2020 - NOV 13, 2023

Vehicle 6: 2022-2024 AUDI Q4 E-TRON SPORTBACK

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q4 E-TRON SPORTBACK: 3028

93U6

Production Dates: SEP 27, 2021 - NOV 08, 2023

VIN Range 1: Begin: WA132BFZ5NP014350 End: WA132BFZXRP033000 ✓ Not sequential

Vehicle 7: 2022-2024 AUDI Q4 E-TRON SUV

Vehicle Type : Body Style : Power Train : NR

Descriptive Information : The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q4 E-TRON: 10618

93U6

Production Dates: SEP 20, 2021 - NOV 09, 2023

VIN Range 1: Begin: WA1M2AFZXPP011347 End: WA1L2BFZXRP033093 ✓ Not sequential

Vehicle 8: 2021-2022 AUDI A7

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

A7: 613 93U6

Production Dates: JUL 24, 2020 - MAY 04, 2022

VIN Range 1: Begin: WAUTPBF23MN001243 End: WAUTPBF26NN050910 ✓ Not sequential

Vehicle 9: 2020-2024 AUDI Q5

Vehicle Type : Body Style : Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q5: 17822 93U6

Production Dates: OCT 17, 2019 - NOV 10, 2023

VIN Range 1: Begin: WA1F2BFY0L2021933 End: WA1E2AFYXR2043985 ✓ Not sequential

Vehicle 10: 2022-2024 AUDI RS E-TRON GT

Vehicle Type : Body Style : Power Train : NR

Descriptive Information : The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

RS E-TRON GT

93U8

Production Dates: DEC 13, 2021 - NOV 28, 2023

VIN Range 1: Begin: WAUAHBFW4N7903235 End: WAUAHBFW0R7900967 ✓ Not sequential

Vehicle 11: 2020-2021 AUDI A8

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

A8: 4 93U8

Production Dates: DEC 10, 2019 - MAY 10, 2021

VIN Range 1: Begin: WAU8HAF83LN008970 End: WAU8HAF85MN021639 ✓ Not sequential

Vehicle 12: 2022-2024 AUDI E-TRON GT

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON GT: 737

93U8

Production Dates: DEC 06, 2021 - DEC 05, 2023

VIN Range 1: Begin: WAUEJBFW0N7005852 End: WAUEJBFW8R7002431 ✓ Not sequential

Vehicle 13: 2019-2024 AUDI E-TRON QUATTRO

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information : The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON QUATTRO: 3001

93U8

Production Dates: MAR 11, 2019 - DEC 07, 2023

VIN Range 1: Begin: WA1VAAGE9KB006679 End: WA16CBGE2RB045693 ✓ Not sequential

Vehicle 14: 2020-2024 AUDI E-TRON SPORTBACK QUATTRO

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

E-TRON SPORTBACK QUATTRO: 1212

93U8

Production Dates: JUN 04, 2020 - DEC 06, 2023

VIN Range 1: Begin: WA13ABGE8LB033323 End: WA1DCBGE0RB045683 ✓ Not sequential

Vehicle 15: 2023-2024 AUDI Q4 E-TRON SPORTBACK

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q4 E-TRON SPORTBACK: 1237

93U8

Production Dates: SEP 29, 2022 - NOV 16, 2023

VIN Range 1: Begin: WA132BFZ8PP003989 End: WA142BFZXRP033194 ✓ Not sequential

Vehicle 16: 2022-2024 AUDI Q4 E-TRON SUV

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q4 E-TRON SUV: 3042

93U8

Production Dates: OCT 09, 2021 - NOV 17, 2023

VIN Range 1: Begin: WA1H2BFZ8NP016325 End: WA1L2BFZ6RP033169 ✓ Not sequential

Vehicle 17: 2021-2021 AUDI A7

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

A7:3 93U8

Production Dates: DEC 03, 2020 - MAR 25, 2021

VIN Range 1: Begin: WAUVPBF29MN039021 End: WAUVPBF25MN078236 ✓ Not sequential

Vehicle 18: 2020-2024 AUDI Q5

Vehicle Type :
Body Style :
Power Train : NR

Descriptive Information: The recall population was determined by production data and includes vehicles that

are equipped with an industrial charging cable without temperature sensors as part

of the Audi e-tron compact charging system.

The recalled products differ from products that were not included in the recall

because they are not equipped with the affected cable.

Q5: 2367 93U8

Production Dates: OCT 17, 2019 - DEC 10, 2023

VIN Range 1: Begin: WA1F2BFY2L2026082 End: WA1G2AFY7R2058596 ✓ Not sequential

Description of Defect:

Description of the Defect: Audi has become aware of cases where melting/overheating occurred at the

industrial socket (NEMA 14 50) when charging with the industrial 220V/240V plug with 40 amperes. All analyzed cases did not show any issues with the charging equipment itself, the root cause always appeared to be household power outlets and/or household wiring/circuit breaker incapable of handling the required electrical current. Should the proper electrical requirements not

be met, the power outlets and/or wiring may be

incapable of handling the required electrical current. In this case use of the

compact charging system

with improper or overburdened 220V power outlets and wiring may, in certain

circumstances, lead to a

risk of overheating of the home infrastructure. In general, the Audi e tron compact charging system can be used for charging at household and industrial sockets. The recall only affects charging with the industrial 220V/240V plug, the charging unit itself and the 110V household charging cable are not affected.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Should the proper electrical requirements not be met, the power outlets and/

or wiring may be incapable of handling the required electrical current. In this case use of the compact charging system with improper or overburdened 220V power outlets and wiring may, in certain circumstances, lead to a risk of overheating of the home infrastructure and eventually cause permanent damage to the house socket and charging cable, increasing the risk of a fire.

Description of the Cause: Electrical household wiring and/or household power outlets incapable of

handling the required electrical current can eventually cause overheating of the home infrastructure and permanent damage to the house socket and

charging cable.

Identification of Any Warning The charging cable may feel hot when touched, e.g. when being unplugged by

that can Occur: the user after charging.

Involved Components:

Component Name 1: Power cable with power plug for industrial sockets

Component Description: Power cable with power plug for industrial sockets (220V/240V) as part of the

original charging equipment

Component Part Number: 7PP 971 678 ED

Supplier Identification:

Component Manufacturer

Name: Harting Automotive GmbH

Address: Marienwerderstrasse 2

Espelkamp Foreign States 32339

Country: Germany

Chronology:

Please see separate document for chronology.

Description of Remedy:

Description of Remedy Program: The relevant power cable with the power plug for industrial sockets (220V/240V/NEMA 14-50) will be replaced by a newly designed cable with temperature sensors. The cable is expected to become available in the second quarter of 2024. Part number of old cable: 7PP971678 ED, part number of new cable: 7PP971678GA.

> In unsold vehicles the affected cable will be removed from the charging equipment before delivery. These customers will receive the newly designed cable at a later point with a separate campaign.

Audi will offer a reimbursement plan under this recall as some vehicles are already out of the manufacturer's warranty.

How Remedy Component Differs The remedy component includes a temperature sensor to detect potential from Recalled Component: overheating due to excess electrical resistance.

Identify How/When Recall Condition Q8 e-tron: Starting with CW 50/23, series vehicles has stopped equipping was Corrected in Production: the vehicles with the affected cable.

e-tron GT: Starting with CW 50/23, series production has stopped

equipping the vehicles with the affected cable.

Q4 e-tron: Starting with CW 47/23, series production has stopped

equipping the vehicles with the affected cable.

Q5 hybrid: Starting with CW 50/23, series production has stopped

equipping the vehicles with the affected cable.

A7 PHEV: No A7 PHEV vehicles have been produced for the US market

since May 2022.

A8 PHEV: No A8 PHEV vehicles have been produced for the US market

since November 2021.

Recall Schedule:

Description of Recall Schedule: Dealers on or before December 19, 2023. Owners: on or before February

09, 2024

Planned Dealer Notification Date : DEC 19, 2023 - DEC 19, 2023 Planned Owner Notification Date : FEB 09, 2024 - FEB 09, 2024

* NR - Not Reported