

Publish Date: July 17, 2013
From: Aftersales Development
Expiration Date: July 31, 2013

DCSnet Message
Important



Subject: **M Performance Power Kit (0Z4A) Temporarily removed from VIA ordering**

Hello,

Due to an engine update starting with July 1st production, the BMW M Performance Power Kit will be unavailable for ordering through VIA (VDC Installed Accessory program). We expect a new Power Kit to be available for the new engine late 2013.

For vehicles produced before July, 2013, please use the following guide to determine which Power Kit part number to order:

1. The vehicles' Plant Integration Level **will need to be verified** prior to ordering the Power Kit.
2. The Plant Integration Level can be checked by performing a Key Read and selecting Vehicle Key Data, then Software Integration.
3. If the Plant Integration Level is older than F020-12-11-500 then the 11 12 2 294 611 kit will need to be ordered. Vehicles requiring the 11 12 2 294 611 kit will need to have a PuMA case submitted for programming assistance by the BMW of North America Technical Services Department.
4. If the Plant Integration Level is between F020-12-11-500 and F020-13-06-50x, the 11 12 2 334 336 kit will need to be ordered.
5. If the Plant Integration Level is F020-13-07-50x or newer, then either 11 12 2 294 611 or 11 12 2 334 336 **cannot be ordered**. Again, we expect a new power kit to be available by late 2013.

Best regards,

Accessory Specialist - Exterior, M Performance and Motorsport

Attachments:

No Attachments

Recipients: BMW Passenger Cars, CC-All
All, All Offerings, All Regions, All Areas, Sales, All
All, All Offerings, All Regions, All Areas, Parts, All